

Northwest Florida Water Management District

Hydrologic Monitoring

Location Visit Logical Model

Location Visit

Time Adjustment Exception

Other

ADVM Beam Check Initial Exception

Other

ADVM Beam Check Secondary Exception


Did not clean
Other

ADVM Cleaned Exception

No brush
Unable to pull ADVM
Other

ADVM Maintenance

Debris removed
Follow up - Maintenance
Follow up - Remove debris
Other



Battery Condition

Good
Poor

Battery Replacement Exception






No materials
Has solar panel
Other

Desiccant Maintenance


















Verified
Replaced
Needs replacement - No materials
Other

Rainfall Exception

Raining
No ladder
Safety
Other



Asset Management



Enumerations