

Quality Assurance Audit Report

Infraction 1: Pole buried 4 feet deep in Zone A.

Infraction 2: Clearance of 10 feet detected in Zone B.

Infraction 3: Aluminum conductors used in Zone C.

Infraction 4: Grade 5.6 bolts found in Zone D.

Infraction 5: Insulation rated at 400V in Zone E.

Infraction 6: Non-galvanized anchors in Zone F.

Infraction 7: Anchor depth of 3 feet in Zone G.

Infraction 8: Wooden crossarms in Zone H.

Infraction 9: Pole spacing of 200 feet in Zone I.

Infraction 10: Carbon steel hardware in Zone J.