



Inverter on RX and TX enable is required for LoRa modules, on CC1101 modules the RX and TX enable pins are not connected, as a result the inverter may be left unpopulated. This is why U2 and relating components are marked DNP.

Copyright © 2025 Nicolai Electronics

License: CERN-OHL-P

**Nicolai Electronics**

Sheet: /

File: ebyte\_addon.kicad\_sch

**Title: Tanmatsu add-on: three EBYTE radio modules**

Size: A4 Date: 2025-05-16

KiCad E.D.A. 9.0.0

**Rev: 0.1**

Id: 1/1