


A

Thursday, February 14, 2019 5:21 PM




Motor Control

User Interface

Safety

ADCs are unlikely to be at 0 or maximum value so it might be due to disconnection of sensor

Monitor LV supplies to asses wether the voltages are appropriate



System