









AC SUPPLY
110/220 VAC

CONNECTOR FOR
CONTROLLER PCB

GND	SCL	3V3
SDA	AD0	CS

2A FUSE

FLOW SENSOR
SEN-FM18T10

TEMPERATURE
SEN-FM18T10

PMP-450
TACHOMETER

PMP-450
SWITCHED ON
CONTROL

SPARE
DIGITAL
INPUT 1

SPARE
DIGITAL
INPUT 2

SPARE
DIGITAL
INPUT 3

VOLTAGE
CONTROL
VLX-450

SPARE
ANALOG
INPUT 2

H3

0-5V

Closed=
PullDown

JP1

AIGUA

12VDC

HLK-20M12

TEMPERATURE 1
SEN-AP008B

TEMPERATURE 2
SEN-AP008B

SPARE
DIGITAL
INPUT 1

SPARE
DIGITAL
INPUT 2

SPARE
DIGITAL
INPUT 3

VOLTAGE
CONTROL
VLX-450

SPARE
ANALOG
INPUT 2

H3

0-5V

Closed=
PullDown

JP1

AIGUA

12VDC

HLK-20M12

TEMPERATURE 1
SEN-AP008B

TEMPERATURE 2
SEN-AP008B

AUGIA
SENSOR BOARD V.1





