



## Defect Photo Report

Structure No	N002_27N_B145
Structure Name	oThongathi Estates Bridge 4
Inspection Date	2016-07-04
OCI	93.90

Thumbnail	Description
	<p><b>Photo Direction:</b> W</p> <p><b>Consultant Description:</b> DSC0618.JPG</p> <p><b>Photo Number:</b></p> <p><b>Repair Activity:</b> 04. Approach Embankment Protection Works-04.401. Apply weed killer/ant poison and remove growth</p> <p><b>Remarks:</b></p>
	<p><b>Photo Direction:</b> N</p> <p><b>Consultant Description:</b> DSC0630.JPG</p> <p><b>Photo Number:</b></p> <p><b>Repair Activity:</b> 17. Expansion Joints-17.302. Joint cover plates (replace and refit)</p> <p><b>Remarks:</b></p>

## Defect Photo Report

Structure No	N002_27N_B145
Structure Name	oThongathi Estates Bridge 4
Inspection Date	2016-07-04
OCI	93.90