

DOCKING PROGRESS REPORT – Day 10	
Ship Name	GAS NURI ARIZONA
Type of Docking	INTERMEDIATE SURVEY V
Location	Semarang
Main Contractor	PT . YWTS
Date	20 July 2018

PHOTO REPORT



Main deck after application first layer anti corrosive paint



Windlass hydraulic pipe has been renewed



Forecastle blower fan has been reinstalled after repair



Installation staging to dismantle cargo pipe



Main deck after application first layer anti corrosive paint



Bunker pipe line has been renewed



Main deck after application first layer anti corrosive paint



In progress renew vinyl floor in mess room