



NOTES: Cut circular features on lathe first, then mill flat edges

UNLESS OTHERWISE SPECIFIED: DIMENSIONS ARE IN INCHES TOLERANCES: 0.X ± 0.1 0.XX ± 0.01 0.XXX ± 0.005				FINISH:			DEBURR AND BREAK SHARP EDGES		DO NOT SCALE DRAWING	REVISION
	NAME	SIGNATURE	DATE						TITLE:	
DRAWN										
CHK'D										
APPV'D										
MFG									DWG NO.	
Q.A										
									A3	
									SCALE:10:1	
									SHEET 1 OF 1	