

HSS Inspection Report

Date : 06 Sep 2025
Page : 1 of 4

Report Number: SIS2522996 Inspection Date/Time: 05 Sep 2025 19:30
06 Sep 2025 04:05
Workplace: PPT3,PPT2
Inspectors: MUHAMMAD JAMALULLAIL BIN MAHADI, SR OPS EXEC, YOD, PSA
AUSTIN CHUE, SR OPS EXEC, YOD, PSA


YARD - X31 & T09 - PM/HAULIER/IGH OPS

Inspected on: 05 Sep 2025 23:33


CheckList

✓	SWP COMPLIANCE - DRIVING WITHIN CHASSIS LANE/SAFE DISTANCE FROM FRONT PM/REVERSE WITHOUT GUIDANCE/PROPER POSITION WITHIN SLOT FOR MOUNTING/OFFLOADING
✓	SWP COMPLIANCE - OBEY TRAFFIC RULES (STOPPED BEFORE WHITE STOP LINE BEFORE PROCEEDING TO NEXT LOCATION)

Description / Immediate Action	Follow Up / Remarks
<p>Team did a CCTV inspection at FM yard blocks to check on PPM compliance to SWP.</p> <p>-Firstly, It was observed that PPM 140 stopped before the STOPLINE at the end of X31 before proceeding to his next location.</p> <p>- Next, It was observed that PPM 672 was observed to be maintaining 2X20 footer safety distance from the front PM while awaiting his turn to mount at FM yard T09.</p> <p>-Both PPM driver 140 & 672 was commended for complying to SOPs and for continuing to always practice safe driving habits.</p> <p>-Both PPM driver 140& 672 was reminded to report any hazards immediately to control center.</p>	<p>SWP Complied/SBR issued.</p>



Caption : PM 140 stopped at the STOP LINE at the end of X31, checked for clear traffic before moving off.



Caption : PPM 672 40FT SAFETY DISTANCE at U31

HSS Inspection Report

Personnel

Person	Company	NISR / SBR
MOHD RIZZWAN BIN MOHMAD MAJIT	S M S MARINE PTE LTD	/ SBR Ref No: SBR202509069604
THOMAS RENGADASAN		/ SBR Ref No: SBR202509069605


YARD - X31 & L10 - HYSTER OPS

Inspected on: 06 Sep 2025 00:42


CheckList

✓	FM Stopped before the white line and checked traffic clearance before reversing out from the yard slot
✓	FM gantry followed SWP aspects with spreader raised to 3 high and closed to 20 footer

Description / Immediate Action	Follow Up / Remarks
<p>Team did a CCTV inspection at FM yard X31 & L10 to check on FM compliance to SWP.</p> <p>- At FM yard X31, FM061 was observed to have come to a complete stop before the white line and check for traffic before further moving out from the yard slot.</p> <p>- Next, at FM yard L10, team observed FM060 operator adhered to SOP when gantrying from bigger to smaller slot with 20 footer spreader close and raised to 3 high.</p> <p>-Team commended both the FM operators for complying to SWP and also reminded the FM operators to report any hazard immediately to his superiors and/or control centre.</p>	<p>SWP Complied/SBR issued.</p>



Caption : FM 061 stopped white line before reversing



Caption : FM 060 gantry followed SWP aspects with spreader raised to 3 high and closed to 20 footer

Personnel

Person	Company	NISR / SBR
CHOONG KAH KENG		/ SBR Ref No: SBR202509069606
SIVABALAN PUSHPA SEGARAN	GKE SERVICES PTE LTD	/ SBR Ref No: SBR202509069607

HSS Inspection Report


YARD - Street of WX & XY - YC GANTRY

Inspected on: 06 Sep 2025 01:30


CheckList

✓	SWP COMPLIANCE - LINEAR AND CROSS GANTRY
---	--

Description / Immediate Action	Follow Up / Remarks
-Team conducted inspection at Terminal 3 RTG yard blocks to ensure that RTG operators ensure traffic clearance and no obstruction at the gantry path before proceed out from the RTGs block.	SWP Complied/SBR issued.



Caption : RTG 557 ensure traffic clearance during gantry operation



Caption : RTG 328 ensure traffic clearance during gantry operation

Personnel

Person	Company	NISR / SBR
RICKEY CHUA		/ SBR Ref No: SBR202509069608
MOHAMAD ZAIRUDDIN BIN ABIDEN		/ SBR Ref No: SBR202509069609

YARD - Street of XY - PM/HAULIER/IGH OPS


Inspected on: 05 Sep 2025 19:45

CheckList

✗	SWP COMPLIANCE - HAULIER FAIL TO GIVE WAY TO RTG DOING GANTRY OPS
---	---

Description / Immediate Action	Follow Up / Remarks
At around 1938hrs, AOC4/5 reported a haulier XE 7745C failed to stop to give way to RTG 553 doing gantry ops at the street of XY. His actions caused RTG 553 to use E-Stop (Near Miss).	Failed to comply with SWP/NISR S2025005054 issued.

HSS Inspection Report



Caption : XE 7745C failed to give way to RTG doing gantry ops
