

# HSS Inspection Report

Date : 27 Sep 2025  
Page : 1 of 3

Report Number: SIS2525099      Inspection Date/Time: 27 Sep 2025 03:47  
27 Sep 2025 03:59  
Workplace: PPT2,PPT3  
Inspectors: HAIDAR BIN JUNIDI, OPS EXEC, YOD, PSA  
AUSTIN CHUE, SR OPS EXEC, YOD, PSA

## YARD - K11 - HYSTER OPS

Inspected on: 27 Sep 2025 03:49

### CheckList

✓	SWP COMPLIANCE - FM GANTRY
---	----------------------------

Description / Immediate Action	Follow Up / Remarks
CCTV Inspection was conducted at K11. -PFM056 operator was observed to have adhered to SOP when gantry to bigger slot for PM offloading. It had its spreader retracted to 20ft and hoisted to high.  -PFM056 operator was commended for complying to SOP and to continue practicing good safety habits at all times. -PFM056 operator was reminded to report any hazard immediately to his superiors or control center.	SBR awarded



Caption : PFM056 on gantry complying with the safety SOP aspects.

### Personnel

Person	Company	NISR / SBR
LEONG WEI PING		/ SBR Ref No: SBR2025092710354

# HSS Inspection Report


## YARD - T09 - PM/HAULIER/IGH OPS

Inspected on: 27 Sep 2025 03:51

### CheckList

✓	SWP COMPLIANCE - DRIVING WITHIN CHASSIS LANE/SAFE DISTANCE FROM FRONT PM/REVERSE WITHOUT GUIDANCE/PROPER POSITION WITHIN SLOT FOR MOUNTING/OFFLOADING
---	---

Description / Immediate Action	Follow Up / Remarks
CCTV inspection was conducted at T09. -It was observed that PPM678 driver adhered to waiting SOP. The driver stopped 1 x 40ft container length away from the mounting slot while waiting for the FM to complete its task. -PPM678 driver was commended for complying to SOP and to continue practicing good safety habits at all times. -PPM678 driver was reminded to report any hazard immediately to his superiors or control center.	SBR awarded



Caption : PPM678 keeping the safe distance while in queue for the container to be mounted

### Personnel

Person	Company	NISR / SBR
LIM KIN SOONG		/ SBR Ref No: SBR2025092710355

## YARD - PM/HAULIER/IGH OPS

Inspected on: 27 Sep 2025 03:55

### CheckList


✓	SWP COMPLIANCE - DRIVING WITHIN CHASSIS LANE/SAFE DISTANCE FROM FRONT PM/REVERSE WITHOUT GUIDANCE/PROPER POSITION WITHIN SLOT FOR MOUNTING/OFFLOADING
---	---

Description / Immediate Action	Follow Up / Remarks
CCTV inspection was conducted at blk U31 -It was observed that PPM737 stopped before the STOPLINE before moving off. -PPM737 driver was commended for complying to SOPs and to continue practicing safe driving habits at all times. -PPM737 driver was reminded to report any hazard immediately to control center.	SBR awarded

# HSS Inspection Report



Caption : PPM737 stopped at the STOP LINE, checked for clear traffic before moving off



Caption : PPM737 stopped at the STOP LINE, checked for clear traffic before moving off

## Personnel

Person	Company	NISR / SBR
VENKATESAN VIGNESH	S M S MARINE PTE LTD	/ SBR Ref No: SBR2025092710356


## YARD - T09 - HYSTER OPS

Inspected on: 27 Sep 2025 03:57

## CheckList

✓	SWP COMPLIANCE
---	----------------

Description / Immediate Action	Follow Up / Remarks
Team did a CCTV inspection at T09 to check on FM compliance to SWP. -FM055 was assigned to do ship operations offloading to T09 -He was observed to adopt 3-step hoist when mounting 1X40 footer at a time to the DST and ensure PM is stationary before offloading container from the chassis. -Team commended him for practicing 3 step hoist and also ensure that PM are stationary when handling containers to the chassis.	SBR awarded



Caption : FM 055 offloading ops, handled 1X40 footer at a time for DST

## Personnel

Person	Company	NISR / SBR
RYAN KOK		/ SBR Ref No: SBR2025092710357