

HSS Inspection Report

Date : 09 Sep 2025
Page : 1 of 4

Report Number: SIS2523265 Inspection Date/Time: 08 Sep 2025 23:00
09 Sep 2025 00:00
Workplace: PPT2
Inspectors: ABDUL HAKIM BIN YUSOF, SR OPS EXEC, YOD, PSA
AUSTIN CHUE, SR OPS EXEC, YOD, PSA

YARD - K11 - HYSTER OPS

Inspected on: 08 Sep 2025 23:18


CheckList

✓	SWP COMPLIANCE
---	----------------

Description / Immediate Action	Follow Up / Remarks
It was observed that FM039 operator complied with SOP when mounting for PMs at yard block K11. FM operator followed 3-step mounting rules for all PMs. FM operator was commended for complying to SOPs and reminded to continue practicing them. FM operator was also reminded to report any hazard immediately to his superiors and / or control centre.	SOP complied / SBR awarded



Caption : FM039 Mounting Operations



Caption : FM039 Mounting Operations

Personnel

Person	Company	NISR / SBR
TAN ENG CHUAN	S M S MARINE PTE LTD	/ SBR Ref No: SBR202509099680

YARD - K11 - PM/HAULIER/IGH OPS


Inspected on: 08 Sep 2025 23:19

CheckList

HSS Inspection Report

✓	SWP COMPLIANCE - DRIVING WITHIN CHASSIS LANE/SAFE DISTANCE FROM FRONT PM/REVERSE WITHOUT GUIDANCE/PROPER POSITION WITHIN SLOT FOR MOUNTING/OFFLOADING
---	---

Description / Immediate Action	Follow Up / Remarks
<p>It was observed that PM8263 after mounting operations at block K11, stopped before the STOPLINE of the chassis lane, checked for oncoming traffic, before moving off.</p> <p>PM driver was commended for complying to SOPs and reminded to continue to practice safe driving habits.</p> <p>PM driver was also reminded to report any hazards immediately to control centre.</p>	SOP complied / SBR awarded



Caption : PM8263 stopped at the STOP LINE, checked for clear traffic before moving off

Personnel

Person	Company	NISR / SBR
ANBAZHAGAN NAVEEN	CALL LADE ENTERPRISES PTE LTD	/ SBR Ref No: SBR202509099681

YARD - L11 - PM/HAULIER/IGH OPS


Inspected on: 08 Sep 2025 23:23

CheckList

✓	SWP COMPLIANCE - DRIVING WITHIN CHASSIS LANE/SAFE DISTANCE FROM FRONT PM/REVERSE WITHOUT GUIDANCE/PROPER POSITION WITHIN SLOT FOR MOUNTING/OFFLOADING
---	---

Description / Immediate Action	Follow Up / Remarks
<p>It was observed that PM8359 waiting at block L11, maintained a 40ft distance from the front chassis.</p> <p>PM driver was commended for complying to SOPs and reminded to continue practicing them.</p> <p>PM driver was reminded to report any hazard immediately to his superiors and / or control centre.</p>	SOP complied / SBR awarded

HSS Inspection Report



Caption : PM8359 maintained a 40ft distance from the front chassis

Personnel

Person	Company	NISR / SBR
AISYAH SYAFIKA BINTI ABD RAZAK	CALL LADE ENTERPRISES PTE LTD	/ SBR Ref No: SBR202509099682


YARD - M12 - HYSTER OPS

Inspected on: 08 Sep 2025 23:46

CheckList

✓	SWP COMPLIANCE
---	----------------

Description / Immediate Action	Follow Up / Remarks
<p>It was observed that FM056 operator adhered to SOP when on gantry from one location to another. It had its spreader closed to 20ft and raised to 3 high.</p> <p>FM operator was commended for complying to SOPs and reminded to continue practicing them.</p> <p>FM operator was also reminded to report any hazards immediately to his superiors and/or control centre.</p>	<p>SOP complied / SBR awarded</p>



Caption : FM056 on gantry, with spreader at 20ft and 3 high

HSS Inspection Report

Personnel

Person	Company	NISR / SBR
DYLAN KONG		/ SBR Ref No: SBR202509099683
