

HSS Inspection Report

Date : 11 Sep 2025
Page : 1 of 4

Report Number: SIS2523524 Inspection Date/Time: 11 Sep 2025 11:00
11 Sep 2025 12:00
Workplace: PPT2,PPT3,PPT1
Inspectors: MERVIN HO, SR OPS EXEC, YOD, PSA
JACINTA NISHANTHI D/O DHARMARAJ, OPS EXEC, YOD, PSA


YARD - W09 - PM/HAULIER/IGH OPS

Inspected on: 11 Sep 2025 11:00

CheckList

✗	SWP COMPLIANCE - DRIVING WITHIN CHASSIS LANE/SAFE DISTANCE FROM FRONT PM/REVERSE WITHOUT GUIDANCE/PROPER POSITION WITHIN SLOT FOR MOUNTING/OFFLOADING
---	---

Description / Immediate Action	Follow Up / Remarks
Following a rise in incidents where PM/IGH/Hauliers did not adhere to the SOP, the team carried out a safety inspection at the RTG yard. The inspection revealed that drivers neglected to stop at the designated stop line before exiting the block.	NISR issued



Caption : XF1064T failed to stop at stop line before exiting RTG block W09.

YARD - U/X - YC GANTRY


Inspected on: 11 Sep 2025 11:15

CheckList

✓	SWP COMPLIANCE - LINEAR AND CROSS GANTRY
---	--

Description / Immediate Action	Follow Up / Remarks
Team then conducted inspection at RTG yard blocks to ensure that RTG operators ensure traffic clearance and no obstruction at the gantry path before proceed out from the RTGs block.	SBR awarded

HSS Inspection Report



Caption : RTG547 ensure traffic clearance during gantry operation



Caption : RTG504 ensure traffic clearance during gantry operation

Personnel

Person	Company	NISR / SBR
JAMES LEE		/ SBR Ref No: SBR202509119768
KENT CHO		/ SBR Ref No: SBR202509119769

YARD - HYSTER OPS

Inspected on: 11 Sep 2025 11:30

CheckList

✓	SWP - PERFORMED 3 STEP HOIST DURING MOUNTING/OFFLOADING OPERATION.
---	--

Description / Immediate Action	Follow Up / Remarks
The team then observed FM065 and FM053 to be performing offloading/mounting operations at T31/T09. FMOs were observed to have performed 3 step hoisting of the spreader while offloading/mounting. After offloading/mounting the container from the PM chassis, FMOs were observed to have reversed to a safe distance before giving the instruction to 'PMGO'. They commended on their compliance to the SWP and reminded not to perform any self recovery on their FM and to inform control or the SR team should they encounter any issues. They acknowledged the reminders and assured the team that they will continue to do so.	SBR awarded

HSS Inspection Report



Caption : FM65 performing offloading operations at T31



Caption : FM53 performing offloading operations at T09

Personnel

Person	Company	NISR / SBR
MUHAMMAD ZULL BIN JAMALUDIN		/ SBR Ref No: SBR202509119770
TAN SAY KWAN ANDRE	GKE SERVICES PTE LTD	/ SBR Ref No: SBR202509119771

YARD - J13 - HYSTER OPS

Inspected on: 11 Sep 2025 11:45

CheckList

✓	SWP - PERFORMED 3 STEP HOIST DURING MOUNTING/OFFLOADING OPERATION.
---	--

Description / Immediate Action	Follow Up / Remarks
<p>Lastly, The team then turned their attention to J13 where RS operations was ongoing. The team observed that RSO803 had followed ensure that his surroundings were clear while performing the shuffling and complied with the 3 step hoisting procedure of the spreader while lifting the container. In addition, RSO803 retracted the boom all the way and lower the container to the ground in compliance with the SWP. RSO803 was also reminded to monitor his Linear Load Moment Indicator and stop work immediately if the indicator is in the yellow region. RSO803 acknowledged the reminders and ensured he will continue to work safe for both himself and safety of others.</p>	<p>SBR awarded</p>

HSS Inspection Report



Caption : RS803 performing offloading at J13.

Personnel

Person	Company	NISR / SBR
JOHN CHIN YEE MING		/ SBR Ref No: SBR202509119772
