

HSS Inspection Report

Date : 30 Sep 2025
Page : 1 of 4

Report Number: SIS2525386 Inspection Date/Time: 29 Sep 2025 20:05
30 Sep 2025 03:25
Workplace: PPT2,PPT3
Inspectors: HAIDAR BIN JUNIDI, OPS EXEC, YOD, PSA
AUSTIN CHUE, SR OPS EXEC, YOD, PSA

YARD - Street of T/U - PM/HAULIER/IGH OPS

Inspected on: 29 Sep 2025 20:06

CheckList

✗	SWP COMPLIANCE - GIVING WAY TO RTG GANTRY
---	---

Description / Immediate Action	Follow Up / Remarks
IPM 054 driver failed to adhere to SOP by failing to give way to RTG 332 performing gantry operation, along street TU.	NISR ISSUED



Caption : Failing to give way to RTG 332 performing gantry operation

Personnel

Person	Company	NISR / SBR
LOK KAM FOOK	KANG LOGISTICS P L	NISR Ref No: S2025005457

YARD - U31 - PM/HAULIER/IGH OPS

Inspected on: 30 Sep 2025 03:15

CheckList

✓	SWP COMPLIANCE - DRIVING WITHIN CHASSIS LANE/SAFE DISTANCE FROM FRONT PM/REVERSE WITHOUT GUIDANCE/PROPER POSITION WITHIN SLOT FOR MOUNTING/OFFLOADING
---	---

Description / Immediate Action	Follow Up / Remarks
--------------------------------	---------------------

HSS Inspection Report

CCTV inspection was conducted at street TU. -It was observed that PPM193 stopped before the STOPLINE before moving off. -PPM193 driver was commended for complying to SOPs and to continue practicing safe driving habits at all times. -PPM193 driver was reminded to report any hazard immediately to control center.	SBR awarded.
--	--------------



Caption : PPM193 stopped at the STOP LINE, checked for clear traffic before moving off

Personnel

Person	Company	NISR / SBR
SETHIYATHOPE RAVI VINOTH		/ SBR Ref No: SBR2025093010400

YARD - L10 - HYSTER OPS


Inspected on: 30 Sep 2025 03:18

CheckList

✓	SWP COMPLIANCE - DST OPS
---	--------------------------

Description / Immediate Action	Follow Up / Remarks
Team did a CCTV inspection at L10 to check on FM compliance to SWP. -FM060 was assigned to do ship operations offloading to L10 -He was observed to adopt 3-step hoist when offloading 1X40 footer at a time from the DST and ensure PM is stationary before offloading container from the chassis. -Team commended him for practicing 3 step hoist and also ensure that PM are stationary when handling containers from the chassis.	SBR awarded.

HSS Inspection Report



Caption : FM 060 offloading ops, handled 1X40 footer
at a time for DST

Personnel

Person	Company	NISR / SBR
SIVABALAN PUSHPA SEGARAN	GKE SERVICES PTE LTD	/ SBR Ref No: SBR2025093010401


YARD - L10 - PM/HAULIER/IGH OPS

Inspected on: 30 Sep 2025 03:23

CheckList

✓	SWP COMPLIANCE - DRIVING WITHIN CHASSIS LANE/SAFE DISTANCE FROM FRONT PM/REVERSE WITHOUT GUIDANCE/PROPER POSITION WITHIN SLOT FOR MOUNTING/OFFLOADING
---	---

Description / Immediate Action	Follow Up / Remarks
CCTV inspection was conducted at L10. -It was observed that PPM144 driver adhered to waiting SOP. The driver stopped 1 x 40ft container length away from the mounting slot while waiting for the FM to complete its task. -PPM144 driver was commended for complying to SOP and to continue practicing good safety habits at all times. -PPM144 driver was reminded to report any hazard immediately to his superiors or control center.	SBR awarded.



Caption : PPM144 keeping the safe distance while in
queue for the container to be offloaded

Personnel

Person	Company	NISR / SBR
--------	---------	------------

HSS Inspection Report

LAKSHMANRAJ PRASATH		/ SBR Ref No: SBR2025093010402
---------------------	--	--------------------------------
