






## 3phase Output to Motor




## Power IN






## MCU commutation Interface



PhaseA+PhaseB currents scaled(Required in FOC) +  
3phase voltage scaled(Required for  
sensoreless operation and may  
be needed for FOC)



## Hall Sensor Interface



Sheet: /Connectors/  
File: connectors.kicad\_sch

Title:

Size: A4  
KiCad E.D.A. 9.0.0

Date:

Rev:  
Id: 2/2