

Navy Admin Textbook Sample

http://navyadministration.tpub.com/14067/css/14067_139.htm

Magnetic to Compass: +W (or -E) deviation. Use left axis.
Compass to Magnetic: +E (or -W) deviation. Use right axis

To convert directly between Magnetic, Compass and True bearings download
a conversion rose from http://www.omnirose.com/deviation_tables/27/

