

**ARM<sup>®</sup> Cortex<sup>®</sup>-M**  
**32-bit Microcontroller**

**NANO102/112 CMSIS Series BSP**  
**Revision History**

*The information described in this document is the exclusive intellectual property of Nuvoton Technology Corporation and shall not be reproduced without permission from Nuvoton.*

*Nuvoton is providing this document only for reference purposes of NuMicro microcontroller based system design. Nuvoton assumes no responsibility for errors or omissions.*

*All data and specifications are subject to change without notice.*

For additional information or questions, please contact: Nuvoton Technology Corporation.

[www.nuvoton.com](http://www.nuvoton.com)

**Revision 3.02.002** (Released 2017-03-10)

1. Fixed smartcard driver and library behaviors that do not comply with EMV2000 spec.
2. Updated SC\_ReadSimPhoneBook sample code to support SIM card with CHV1 disabled.
3. Updated startup\_Nano1X2Series.s to remove the disable POR code.

**Revision 3.02.001** (Released 2016-07-28)

1. Updated CMSIS to v4.5.0.
2. Added sample code ADC\_PWMTrigger.
3. Fixed the TEMPCTL register offset definition error.
4. Minor bug fixes.

**Revision 3.02.000** (Released 2015-07-08)

1. Removed CLK\_APBCLK\_TK\_EN macro in clk.h.
2. Removed ACMP\_ENABLE\_OUTPUT\_INVERSE and ACMP\_DISABLE\_OUTPUT\_INVERSE macros in acmp.h.
3. Removed  
FMC\_EnableAPUpdate(), FMC\_DisableAPUpdate(), FMC\_EnableLDUpdate(),  
FMC\_DisableLDUpdate(), FMC\_EnableConfigUpdate(), and  
FMC\_DisableConfigUpdate() in fmc.h and fmc.c.
4. Removed all IAR projects' [Debug] configuration.
5. Modified all IAR projects' reset entry as Reset\_Handler.
6. Modified all Keil projects' device type as NANO112VC2AN.
7. Renamed SYS\_IRCTRIMINT\_32KERR\_ENNT as SYS\_IRCTRIMINT\_32KERR\_INT in sys.h.
8. Renamed CHER as CHEN in adc.h.
9. Renamed SYS\_IPRSTCTL2\_LCD to SYS\_IPRST\_CTL2\_LCD\_RST\_Msk in lcd.h.
10. Renamed StdDriver sample GPIO to GPIO\_IOTest.
11. Renamed StdDriver sample CRC to CRC\_CCITT.
12. Renamed StdDriver sample PDMA to PDMA\_Memory.
13. Renamed StdDriver sample SYS to SYS\_Control.
14. Fixed SYS\_PA\_L\_MFP\_PA0\_MFP\_GPA0 and SYS\_PA\_L\_MFP\_PA0\_MFP\_GPA0 implementation errors in sys.h.
15. Fixed DMA\_CRC\_CTL\_CRC\_RST\_Msk implementation error in crc.h.
16. Fixed PDMA\_IS\_CH\_BUSY implementation error in pdma.h.
17. Fixed ADC\_SET\_INPUT\_CHANNEL() implementation error in adc.h.
18. Fixed SC\_SET\_STOP\_BIT\_LEN implementation error in sc.h.
19. Fixed UART\_IS\_TX\_EMPTY implementation error in uart.h.
20. Fixed LCD\_CPUMP\_DIV128 implementation error in lcd.h.
21. Fixed PWM\_ENABLE\_OUTPUT\_INVERTER() error in pwm.h.
22. Fixed ADC\_IS\_DATA\_OVERRUN() and ADC\_IS\_DATA\_VALID() errors in adc.h.
23. Fixed I<sup>2</sup>C register CON2 and STATUS2 offset bug in Nano1X2Series.h.
24. Fixed the bug that timer\_delay() set prescale to wrong register in timer.c.
25. Fixed ACMP\_SetSigmaDeltaConv() parameter u32PosPin implementation bug in acmp.c.
26. Fixed RTC\_CLEAR\_TAMPER\_FLAG() implementation bug rtc.h.
27. Fixed Frame counter calculate error of LCD\_EnableFrameCounter() in lcd.c.
28. Fixed SYS\_IsRegLocked() return value bug in sys.c.
29. Fixed SCUART\_Open() and SCUART\_SetLineConfig() baudrate calculation prescale setting error in scuart.c.

30. Fixed bug of SPI\_EnableAutoSS () and SPI\_SetBusClock () in spi.c. Cleared bit mask of register field before writing input parameter to it.
31. Modified UART\_SelectIrDAMode() to reload UART clock before calculating baudrate in uart.c.
32. Modified SYS\_LockReg() and SYS\_UnlockReg() as inline function in sys.h.
33. Modified RTC\_WRITE\_KEY program flow to avoid be overwritten by ISR, in rtc.c.
34. Modified GP\_DBNCECON\_PUEN\_\* as GP\_DBNCECON\_DBCLKSEL\_\* in Nano1X2Series.h.
35. Modified Timer\_Open() to not start timer in it, in timer.c.
36. Disabled Rx before raising RST high during cold reset in SmartCardLib library.
37. Check SC\_RST and SC\_DAT\_O pin status during deactivation in SmartCardLib library.
38. Added I2C\_ClearIntFlag() function in i2c.c.
39. Added macros CLK\_PLLCTL\_\*MHz\_HXT and CLK\_PLLCTL\_\*MHz\_HIRC for setting PLLCTL vaule in clk.h.
40. Added ACMP\_SELECT\_P in acmp.h.
41. Added SYS\_GET\_IRCTRIM\_INT\_FLAG() and SYS\_CLEAR\_IRCTRIM\_INT\_FLAG() in sys.h.
42. Added UART\_FUNC\_SEL\_LIN macro in uart.h.
43. Added CLK\_EnableSysTick() and CLK\_DisableSysTick() in clk.c.
44. Added SYS\_EnableIRCTrim() and SYS\_DisableIRCTrim() in sys.c.
45. Added UART\_SelectLINMode() in uart.c.
46. Added Nano112 learning board samples in Nu-LB-NANO112 folder.
47. Added sample SYS\_TrimIRC to StdDriver.
48. Added sample Timer\_Wakeup to StdDriver.
49. Added sample UART\_PDMA to StdDriver.

### Revision 3.01.000 (Released 2014-11-28)

---

1. Fixed GPIO\_DISABLE\_DIGITAL\_PATH(), GPIO\_ENABLE\_DIGITAL\_PATH(), GPIO\_DISABLE\_DOUT\_MASK(), GPIO\_ENABLE\_DOUT\_MASK(), GPIO\_DISABLE\_PULL\_UP(), and GPIO\_ENABLE\_PULL\_UP() implementation error.
2. Fixed SYS\_PC\_L\_MFP\_PC0\_MFP\_LCD\_S11, SYS\_PC\_L\_MFP\_PC0\_MFP\_LCD\_S18, SYS\_PC\_L\_MFP\_PC0\_MFP\_LCD\_S22, SYS\_PC\_H\_MFP\_PC10\_MFP\_I2C1\_SCL, SYS\_PC\_H\_MFP\_PC11\_MFP\_I2C1\_SDA, SYS\_PD\_H\_MFP\_PD13\_MFP\_EINT1, SYS\_PD\_H\_MFP\_PD10\_MFP\_LCD\_COM0, SYS\_PD\_H\_MFP\_PD10\_MFP\_LCD\_COM0, SYS\_PD\_H\_MFP\_PD9\_MFP\_LCD\_COM1, SYS\_PD\_H\_MFP\_PD8\_MFP\_LCD\_COM2, SYS\_PF\_L\_MFP\_PF5\_MFP\_ICE\_DAT, and SYS\_PF\_L\_MFP\_PF4\_MFP\_ICE\_CLK definition errors.
3. Fixed SYS\_DISABLE\_BOD\*(), and SYS\_ENABLE\_BOD\*() implementation error.
4. Fixed PDMA\_WIDTH\_\* definition error.
5. Fixed PWM\_ConfigOutputChannel() and PWM\_ConfigCaptureChannel() PWM channel 2 and 3 clock setting error.
6. Fixed SPI\_SET\_SSx\_LOW(), SPI\_SET\_SSx\_HIGH(), SPI\_CLR\_3WIRE\_START\_INT\_FLAG(), and SPI\_CLR\_UNIT\_TRANS\_INT\_FLAG() implementation error.
7. Fixed SPI\_Open(), SPI\_SetBusClock() and SPI\_GetBusClock() clock frequency calculation.

8. Fixed I2C\_Open(), I2C\_GetBusClockFreq(), and I2C\_SetBusClockFreq() clock frequency calculation error.
9. Replaced the \*\_MFP\_TIMERx\_EXT setting with \*\_MFP\_TIMERx\_CNT and \*\_TIMERx\_OUT.
10. Renamed \*\_MFP\_CKOHZ to \*\_MFP\_CLK\_Hz.
11. Renamed SYS\_PA\_L\_MFP\_PA5\_MFP\_SC2\_RST to SYS\_PA\_L\_MFP\_PA5\_MFP\_SC0\_PWR.
12. Renamed SYS\_PA\_H\_MFP\_PA10\_MFP\_SC0\_DAT to SYS\_PA\_H\_MFP\_PA10\_MFP\_SC0\_CLK.
13. Renamed SYS\_PA\_H\_MFP\_PA12\_MFP\_I2C1\_SCL to SYS\_PA\_H\_MFP\_PA12\_MFP\_I2C0\_SCL.
14. Renamed SYS\_PA\_H\_MFP\_PA15\_MFP\_I2C\_DAT to SYS\_PA\_H\_MFP\_PA15\_MFP\_I2C1\_SDA.
15. Renamed SYS\_PB\_L\_MFP\_PB3\_MFP\_I2C\_DAT to SYS\_PB\_L\_MFP\_PB3\_MFP\_I2C0\_DAT.
16. Renamed SYS\_PB\_L\_MFP\_PB5\_MFP\_SPI2\_MOSI1 to SYS\_PB\_L\_MFP\_PB5\_MFP\_SPI1\_MOSI1.
17. Renamed SYS\_PB\_L\_MFP\_PB7\_MFP\_CD to SYS\_PB\_L\_MFP\_PB7\_MFP\_SC0\_CD.
18. Renamed SYS\_PB\_H\_MFP\_PB10\_MFP\_SPI1\_MOSI1 to SYS\_PB\_H\_MFP\_PB10\_MFP\_SPI0\_MOSI1.
19. Renamed SYS\_PD\_L\_MFP\_PD7\_MFP\_LCD\_S3 to SYS\_PD\_L\_MFP\_PD7\_MFP\_LCD\_COM3.
20. Renamed SYS\_PD\_H\_MFP\_PD11\_MFP\_LCD\_DH1 to SYS\_PD\_H\_MFP\_PD11\_MFP\_LCD\_DH2.
21. Renamed SYS\_PD\_H\_MFP\_PD12\_MFP\_LCD\_DH2 to SYS\_PD\_H\_MFP\_PD12\_MFP\_LCD\_DH1.
22. Renamed SYS\_PF\_L\_MFP\_PF2\_MFP\_HXT\_OUT to SYS\_PF\_L\_MFP\_PF2\_MFP\_XT1\_IN.
23. Renamed SYS\_PF\_L\_MFP\_PF3\_MFP\_HXT\_IN to SYS\_PF\_L\_MFP\_PF3\_MFP\_XT1\_OUT.
24. Renamed SYS\_PF\_L\_MFP\_PF1\_MFP\_ICE\_CLK to SYS\_PF\_L\_MFP\_PF4\_MFP\_ICE\_CLK.
25. Renamed SYS\_PF\_L\_MFP\_PF0\_MFP\_ICE\_DAT to SYS\_PF\_L\_MFP\_PF5\_MFP\_ICE\_DAT.
26. Updated CLK\_EnableCKO() to set clock source before output enable.
27. Updated I2C\_WAIT\_READY() to clear I2C\_INTSTS\_INTSTS\_Msk before exiting macro.
28. Updated FMC\_Erase() to avoid modifying FMC->ISPCON register setting.
29. Added SYS\_PD\_H\_MFP\_PD11\_MFP\_PWM0\_CH1 definition.
30. Added ADC\_PDMA, ADC\_TimerTrigger, GPIO\_PowerDown, Hard\_Fault\_Sample, PWM\_CapturePDMA, SPI\_TxRxLoopback\_PDMA, SYS\_PLLClockOutput, UART\_FlowCtrl, and UART\_Rx\_Wakeup samples.

#### Revision 3.00.001 (Released 2014-03-31)

1. Improved PWM capture function performance.
2. Added ADC\_SET\_REF\_VOLTAGE macro to configure ADC reference voltage.
3. Minor bug fix.

**Revision 3.00.000** (Released 2014-03-03)

---

1. Renamed I2C\_SetClockBusFreq() to I2C\_SetBusClockFreq().
2. Renamed I2C\_SetSlaveMask() to I2C\_SetSlaveAddrMask().
3. Renamed RTC\_GetDatAndTime() to RTC\_GetDateAndTime().
4. Added Learning Board sample.
5. Moved Smartcard libraries one directory level up to Library\SmartcardLib\.
6. Minor bug fix.

### Important Notice

Nuvoton Products are neither intended nor warranted for usage in systems or equipment, any malfunction or failure of which may cause loss of human life, bodily injury or severe property damage. Such applications are deemed, "Insecure Usage".

Insecure usage includes, but is not limited to: equipment for surgical implementation, atomic energy control instruments, airplane or spaceship instruments, the control or operation of dynamic, brake or safety systems designed for vehicular use, traffic signal instruments, all types of safety devices, and other applications intended to support or sustain life.

All Insecure Usage shall be made at customer's risk, and in the event that third parties lay claims to Nuvoton as a result of customer's Insecure Usage, customer shall indemnify the damages and liabilities thus incurred by Nuvoton.

---

*Please note that all data and specifications are subject to change without notice.  
All the trademarks of products and companies mentioned in this datasheet belong to their respective owners.*