



How to make the HMI Animation run smoother and quicker?

If you want HMI simulation to have a lesser delay, then you can change this setting from the HMI Tag values. Technically, we call it 'Acquisition time'. It's the time that HMI takes to acquire the value from Tags (PLC or HMI Tags)

To change that, kindly navigate to HMI tags and find a column titled “Acquisition Cycle” as shown below:



Following are the ranges available:



You can choose the range as per your requirement. Hope you find this useful.

Regards,

Rajvir Singh