

## **Vehicle Tracking Incident Report**

**Date:** 06 November 2025

**Prepared by:** Pamphille Oluoch

**Department:** Control Room

**Subject:** Report on Vehicle Trackers Malfunction and Investigation Findings

Between the months of **October and November 2025**, it was observed that some vehicles within the company had stopped transmitting location data from the installed vehicle tracking devices, while others were not functioning as expected.

The issue was reported to **ZURI**, the company responsible for the tracker installation, to conduct an inspection and determine the cause of the malfunction. The inspection was carried out on **06 November 2025**, and the following findings were recorded:

**1. Vehicle Registration: KBK 123J**

The tracking device on this vehicle had been **non-functional for 23 days**. Upon inspection, the technician discovered that the **tracker wiring had been cut**. Further investigation revealed that the individual responsible for was **Christopher Mwangi**, an auto-electrician attached to the workshop.

**2. Vehicle Registration: KBA 418A (Game RSV Monitoring)**

The tracking device in this vehicle was found to be **intact and not tampered with**, but was **faulty** and required technical repair or replacement.

The **Head of Workshop, Mr. Samuel**, was informed of the findings and made aware of the involvement of **Mr. Christopher Mwangi** in the tampering of the tracker for vehicle **KBK 123J**. It is recommended that **Human Resources** review the matter for appropriate disciplinary or corrective action.



KBK123J

Cut tracker