



























DOUBLETREE By HILTON JAKARTA KEMAYORAN

2024-12-13 09:00 - 2024-12-13 13:00

NO	Jam	Nama Anggota	Lokasi	Finding	Remarks
1	11:10:04	Muhamad Hermawan	LT 05 WING B		apar di Lt 5 WB kondisi baik
2	11:10:04	Muhamad Hermawan	LT 05 WING B		hydrant di Lt 5 WB kondisi baik
3	11:10:04	Muhamad Hermawan	LT 05 WING B		exit door emergency Lt 5 WB kondisi baik
4	11:10:04	Muhamad Hermawan	LT 05 WING B		pintu kamar coridor Lt 5 WB kondisi tertutup
5	11:10:04	Muhamad Hermawan	LT 05 WING B		koridor Lt 5 WB clear
6	11:17:17	Muhamad Hermawan	LT 05 WING A		Apar coridor WA Lt 5 kondisi baik
7	11:17:17	Muhamad Hermawan	LT 05 WING A		hydrant coridor WA Lt 4 kondisi baik
8	11:17:17	Muhamad Hermawan	LT 05 WING A		wall dalam staircase WA retak
9	11:17:17	Muhamad Hermawan	LT 05 WING A		piintu room Lt 5 WA kondisi baik
10	11:17:17	Muhamad Hermawan	LT 05 WING A		depan room 505 terdapat troli bayi
11	11:23:07	Muhamad Hermawan	LT 03 WING A		baik
12	11:23:07	Muhamad Hermawan	LT 03 WING A		baik
13	11:23:07	Muhamad Hermawan	LT 03 WING A		wall dalam staircase WA rerak
14	11:23:07	Muhamad Hermawan	LT 03 WING A		naik
15	11:23:07	Muhamad Hermawan	LT 03 WING A		baik
16	11:54:03	Muhamad Hermawan	LT 03 POOL 1		baik
17	11:54:03	Muhamad Hermawan	LT 03 POOL 1		baik
18	11:54:03	Muhamad Hermawan	LT 03 POOL 1		baik
19	11:54:03	Muhamad Hermawan	LT 03 POOL 1		koridor lamp depan pintu kaca akses pool mati 1
20	11:55:15	Muhamad Hermawan	LT 03 GYM		baik

NO	Jam	Nama Anggota	Lokasi	Finding	Remarks
21	11:55:15	Muhamad Hermawan	LT 03 GYM		coridor lamp di dalam gym kondisi redup
22	11:58:03	Muhamad Hermawan	LT 03 POOL 2		baik
23	11:58:03	Muhamad Hermawan	LT 03 POOL 2		baik
24	11:58:03	Muhamad Hermawan	LT 03 POOL 2		baik
25	11:58:03	Muhamad Hermawan	LT 03 POOL 2		lampu di infinity pool mati 1
26	12:01:12	Muhamad Hermawan	LT 03 WING B		baik
27	12:01:12	Muhamad Hermawan	LT 03 WING B		baik
28	12:01:12	Muhamad Hermawan	LT 03 WING B		baik
29	12:01:12	Muhamad Hermawan	LT 03 WING B		di staircase Lt 3 WB masih terdapat barang milik vendor jse
30	12:01:18	Muhamad Hermawan	LT 03 WING B		baik
31	12:01:18	Muhamad Hermawan	LT 03 WING B		baik
32	12:01:18	Muhamad Hermawan	LT 03 WING B		baik
33	12:01:18	Muhamad Hermawan	LT 03 WING B		di staircase Lt 3 WB masih terdapat barang milik vendor jse
34	12:01:18	Muhamad Hermawan	LT 03 WING B		baik
35	12:06:07	Muhamad Hermawan	LT 03 AHU ROOM		baik
36	12:06:07	Muhamad Hermawan	LT 03 AHU ROOM		lantai dalam staircase to roof 5 liking, dari jalur AC
37	12:06:07	Muhamad Hermawan	LT 03 AHU ROOM		wall dalam staircase to roof 5 defect
38	12:08:41	Muhamad Hermawan	LT 02 AV ROOM		baik
39	12:08:41	Muhamad Hermawan	LT 02 AV ROOM		baik
40	12:08:41	Muhamad Hermawan	LT 02 AV ROOM		baik
41	12:09:36	Muhamad Hermawan	LT 02 BACK ANGSAANA 3		baik
42	12:09:36	Muhamad Hermawan	LT 02 BACK ANGSAANA 3		baik
43	12:09:36	Muhamad Hermawan	LT 02 BACK ANGSAANA 3		exit lamp samping Angsana 3 redup
44	12:10:39	Muhamad Hermawan	LT 02 STORE BANQUET		baik
45	12:10:39	Muhamad Hermawan	LT 02 STORE BANQUET		baik
46	12:10:39	Muhamad Hermawan	LT 02 STORE BANQUET		wall dalam staircase samping mushola defect
47	12:11:27	Muhamad Hermawan	LT 02 SMOKING AREA		baik
48	12:11:27	Muhamad Hermawan	LT 02 SMOKING AREA		baik
49	12:14:19	Muhamad Hermawan	LT 02 CENDANA 1		baik

NO	Jam	Nama Anggota	Lokasi	Finding	Remarks
50	12:14:19	Muhamad Hermawan	LT 02 CENDANA 1		plafon depan Cendana 1 bolong
51	12:15:47	Muhamad Hermawan	LT 02 PANTRY		baik
52	12:15:47	Muhamad Hermawan	LT 02 PANTRY		baik
53	12:15:47	Muhamad Hermawan	LT 02 PANTRY		koridor lamp depan guest lift Lt 2 mati
54	12:17:20	Muhamad Hermawan	LT 02 KITCHEN BANQUET		baik
55	12:17:20	Muhamad Hermawan	LT 02 KITCHEN BANQUET		baik
56	12:17:20	Muhamad Hermawan	LT 02 KITCHEN BANQUET		coridor lamp coridor kitc bqt mati
57	12:18:36	Muhamad Hermawan	LT 02 STAIRCASE WING B		staircase lamp WB Lt 2 mati
58	12:54:54	Muhamad Hermawan	B.1 DRIVER ROOM		kondisi baik
59	12:54:54	Muhamad Hermawan	B.1 DRIVER ROOM		genangan air depan mushola basement
60			ROOF TOP WING A		
61			ROOF TOP MESIN LIFT		
62			ROOF TOP WING B		
63			LT 15 WING B		
64			LT 15 WING A		
65			LT 12 WING A		
66			LT 12 WING B		
67			LT 11 WING B		
68			LT 11 WING A		
69			LT 10 WING A		
70			LT 10 WING B		
71			LT 09 WING B		
72			LT 09 WING A		
73			LT 08 WING A		
74			LT 08 WING B		
75			LT 07 WING B		
76			LT 07 WING A		
77			LT 06 WING A		
78			LT 06 WING B		
79			LT 03 ROOF TOP		
80			LT 01 BACK OFFICE		
81			LT 01 KITCHEN BOTANY 1		
82			LT 01 KITCHEN BOTANY 2		
83			LT 01 SERVER ROOM		

NO	Jam	Nama Anggota	Lokasi	Finding	Remarks
84			LT 01 GAS ROOM		
85			LT 01 LOADING DOCK		
86			LT 01 GARDEN LOADING DOCK		
87			LT 01 GARDEN BOTANY		
88			LT 01 CAR CHECK		
89			LT 01 VALET PARKING (NEAR BG)		
90			LT 01 NEAR FB OFFICE		
91			LT 01 TRAVO ROOM		
92			LT 01 RAMP IN OUT		
93			B.1 RAMP IN OUT		
94			B.1 PARKIR MOTOR 1		
95			B.1 PARKIR MOTOR 2		
96			B.1 PARKIR MOTOR 3		
97			B.1 STAIRCASE TO LOADING DOCK		
98			B.1 NEAR TRANSIT PUMP		
99			B.1 STORE FB		
100			B.1 LAUNDRY		
101			B.1 MALE LOCKER		
102			B.1 KITCHEN KONGKOW		
103			LT 1 PANTRY		