

Report Patroli (2024-11-01 to 2024-11-06)

No	Tanggal	Task	Point	Status	Description	Petugas
1	2024-11-01	ROOF TOP WING A	PENGECEKAN APAR	-	-	-
2	2024-11-01	ROOF TOP WING A	PENGECEKAN APAR	-	-	-
3	2024-11-01	ROOF TOP WING A	PENGECEKAN APAR	-	-	-
4	2024-11-01	ROOF TOP WING A	PENGECEKAN PANEL	-	-	-
5	2024-11-01	ROOF TOP WING A	PENGECEKAN PANEL	-	-	-
6	2024-11-01	ROOF TOP WING A	PENGECEKAN PANEL	-	-	-
7	2024-11-01	ROOF TOP WING A	PENGECEKAN AREA WING A	-	-	-
8	2024-11-01	ROOF TOP WING A	PENGECEKAN AREA WING A	-	-	-
9	2024-11-01	ROOF TOP WING A	PENGECEKAN AREA WING A	-	-	-
10	2024-11-01	ROOF TOP MESIN LIFT	PENGECEKAN APAR	-	-	-
11	2024-11-01	ROOF TOP MESIN LIFT	PENGECEKAN APAR	-	-	-
12	2024-11-01	ROOF TOP MESIN LIFT	PENGECEKAN APAR	-	-	-
13	2024-11-01	ROOF TOP MESIN LIFT	PENGECEKAN AC DAN PANEL APABILAN TIDAK DIGUNAKAN (OFF)	-	-	-
14	2024-11-01	ROOF TOP MESIN LIFT	PENGECEKAN AC DAN PANEL APABILAN TIDAK DIGUNAKAN (OFF)	-	-	-
15	2024-11-01	ROOF TOP MESIN LIFT	PENGECEKAN AC DAN PANEL APABILAN TIDAK DIGUNAKAN (OFF)	-	-	-
16	2024-11-01	ROOF TOP MESIN LIFT	PENGECEKAN PINTU LIFT & MESIN	-	-	-
17	2024-11-01	ROOF TOP MESIN LIFT	PENGECEKAN PINTU LIFT & MESIN	-	-	-
18	2024-11-01	ROOF TOP MESIN LIFT	PENGECEKAN PINTU LIFT & MESIN	-	-	-
19	2024-11-01	ROOF TOP MESIN LIFT	PENGECEKAN SALKAR APBILA TIDAK DIGUNAKAN DI OFF	-	-	-
20	2024-11-01	ROOF TOP MESIN LIFT	PENGECEKAN SALKAR APBILA TIDAK DIGUNAKAN DI OFF	-	-	-
21	2024-11-01	ROOF TOP MESIN LIFT	PENGECEKAN SALKAR APBILA TIDAK DIGUNAKAN DI OFF	-	-	-
22	2024-11-01	ROOF TOP WING B	PENGECEKAN APAR	Baik	ok	1808071010940004
23	2024-11-01	ROOF TOP WING B	PENGECEKAN APAR	Baik	ok	1808071010940004
24	2024-11-01	ROOF TOP WING B	PENGECEKAN APAR	Baik	ok	1808071010940004

No	Tanggal	Task	Point	Status	Description	Petugas
25	2024-11-01	ROOF TOP WING B	PENGECEKAN AC DAN PANEL APABILAN TIDAK DIGUNAKAN (OFF)	Baik	ok	1808071010940004
26	2024-11-01	ROOF TOP WING B	PENGECEKAN AC DAN PANEL APABILAN TIDAK DIGUNAKAN (OFF)	Baik	ok	1808071010940004
27	2024-11-01	ROOF TOP WING B	PENGECEKAN AC DAN PANEL APABILAN TIDAK DIGUNAKAN (OFF)	Baik	ok	1808071010940004
28	2024-11-01	ROOF TOP WING B	PENGECEKAN KEBERSIHAN AREA	Baik	ok	1808071010940004
29	2024-11-01	ROOF TOP WING B	PENGECEKAN KEBERSIHAN AREA	Baik	ok	1808071010940004
30	2024-11-01	ROOF TOP WING B	PENGECEKAN KEBERSIHAN AREA	Baik	ok	1808071010940004
31	2024-11-01	ROOF TOP WING B	PENGECEKAN AKSES APABILA TIDAK DIGUNAKAN KONDISI TERTUTUP/TERKUNCI	Baik	ok	1808071010940004
32	2024-11-01	ROOF TOP WING B	PENGECEKAN AKSES APABILA TIDAK DIGUNAKAN KONDISI TERTUTUP/TERKUNCI	Baik	ok	1808071010940004
33	2024-11-01	ROOF TOP WING B	PENGECEKAN AKSES APABILA TIDAK DIGUNAKAN KONDISI TERTUTUP/TERKUNCI	Baik	ok	1808071010940004
34	2024-11-01	LT 15 WING B	PENGECEKAN APAR	Baik	oo	1808071010940004
35	2024-11-01	LT 15 WING B	PENGECEKAN APAR	Baik	oo	1808071010940004
36	2024-11-01	LT 15 WING B	PENGECEKAN APAR	Baik	oo	1808071010940004
37	2024-11-01	LT 15 WING B	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
38	2024-11-01	LT 15 WING B	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
39	2024-11-01	LT 15 WING B	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
40	2024-11-01	LT 15 WING B	PENGECEKAN KOORIDOR KAMAR	Baik	ok	1808071010940004
41	2024-11-01	LT 15 WING B	PENGECEKAN KOORIDOR KAMAR	Baik	ok	1808071010940004
42	2024-11-01	LT 15 WING B	PENGECEKAN KOORIDOR KAMAR	Baik	ok	1808071010940004
43	2024-11-01	LT 15 WING B	PENGECEKAN PANEL	Baik	ok	1808071010940004
44	2024-11-01	LT 15 WING B	PENGECEKAN PANEL	Baik	ok	1808071010940004
45	2024-11-01	LT 15 WING B	PENGECEKAN PANEL	Baik	ok	1808071010940004
46	2024-11-01	LT 15 WING B	PENGECEKAN EXIT	Baik	ok	1808071010940004
47	2024-11-01	LT 15 WING B	PENGECEKAN EXIT	Baik	ok	1808071010940004
48	2024-11-01	LT 15 WING B	PENGECEKAN EXIT	Baik	ok	1808071010940004
49	2024-11-01	LT 15 WING A	PENGECEKAN APAR	-	-	-
50	2024-11-01	LT 15 WING A	PENGECEKAN APAR	-	-	-

No	Tanggal	Task	Point	Status	Description	Petugas
51	2024-11-01	LT 15 WING A	PENGECEKAN APAR	-	-	-
52	2024-11-01	LT 15 WING A	PENGECEKAN KORIDOR	-	-	-
53	2024-11-01	LT 15 WING A	PENGECEKAN KORIDOR	-	-	-
54	2024-11-01	LT 15 WING A	PENGECEKAN KORIDOR	-	-	-
55	2024-11-01	LT 15 WING A	PENGECEKAN HYDRANT	-	-	-
56	2024-11-01	LT 15 WING A	PENGECEKAN HYDRANT	-	-	-
57	2024-11-01	LT 15 WING A	PENGECEKAN HYDRANT	-	-	-
58	2024-11-01	LT 15 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
59	2024-11-01	LT 15 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
60	2024-11-01	LT 15 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
61	2024-11-01	LT 15 WING A	PENGECEKAN PINTU KAMAR	-	-	-
62	2024-11-01	LT 15 WING A	PENGECEKAN PINTU KAMAR	-	-	-
63	2024-11-01	LT 15 WING A	PENGECEKAN PINTU KAMAR	-	-	-
64	2024-11-01	LT 12 WING A	PENGECEKAN APAR	Baik	ok	1808071010940004
65	2024-11-01	LT 12 WING A	PENGECEKAN APAR	Baik	ok	1808071010940004
66	2024-11-01	LT 12 WING A	PENGECEKAN APAR	Baik	ok	1808071010940004
67	2024-11-01	LT 12 WING A	PENGECEKAN KORIDOR	Baik	ok	1808071010940004
68	2024-11-01	LT 12 WING A	PENGECEKAN KORIDOR	Baik	ok	1808071010940004
69	2024-11-01	LT 12 WING A	PENGECEKAN KORIDOR	Baik	ok	1808071010940004
70	2024-11-01	LT 12 WING A	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
71	2024-11-01	LT 12 WING A	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
72	2024-11-01	LT 12 WING A	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
73	2024-11-01	LT 12 WING A	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
74	2024-11-01	LT 12 WING A	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
75	2024-11-01	LT 12 WING A	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
76	2024-11-01	LT 12 WING A	PENGECEKAN PINTU KAMAR	Baik	ok	1808071010940004

No	Tanggal	Task	Point	Status	Description	Petugas
77	2024-11-01	LT 12 WING A	PENGECEKAN PINTU KAMAR	Baik	ok	1808071010940004
78	2024-11-01	LT 12 WING A	PENGECEKAN PINTU KAMAR	Baik	ok	1808071010940004
79	2024-11-01	LT 12 WING B	PENGECEKAN APAR	Baik	ok	1808071010940004
80	2024-11-01	LT 12 WING B	PENGECEKAN APAR	Baik	ok	1808071010940004
81	2024-11-01	LT 12 WING B	PENGECEKAN APAR	Baik	ok	1808071010940004
82	2024-11-01	LT 12 WING B	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
83	2024-11-01	LT 12 WING B	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
84	2024-11-01	LT 12 WING B	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
85	2024-11-01	LT 12 WING B	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
86	2024-11-01	LT 12 WING B	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
87	2024-11-01	LT 12 WING B	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
88	2024-11-01	LT 12 WING B	PENGECEKAN PINTU KAMAR	Baik	ok	1808071010940004
89	2024-11-01	LT 12 WING B	PENGECEKAN PINTU KAMAR	Baik	ok	1808071010940004
90	2024-11-01	LT 12 WING B	PENGECEKAN PINTU KAMAR	Baik	ok	1808071010940004
91	2024-11-01	LT 12 WING B	PENGECEKAN KORIDOR	Baik	ok	1808071010940004
92	2024-11-01	LT 12 WING B	PENGECEKAN KORIDOR	Baik	ok	1808071010940004
93	2024-11-01	LT 12 WING B	PENGECEKAN KORIDOR	Baik	ok	1808071010940004
94	2024-11-01	LT 11 WING B	PENGECEKAN APAR	-	-	-
95	2024-11-01	LT 11 WING B	PENGECEKAN APAR	-	-	-
96	2024-11-01	LT 11 WING B	PENGECEKAN APAR	-	-	-
97	2024-11-01	LT 11 WING B	PENGECEKAN HYDRANT	-	-	-
98	2024-11-01	LT 11 WING B	PENGECEKAN HYDRANT	-	-	-
99	2024-11-01	LT 11 WING B	PENGECEKAN HYDRANT	-	-	-
100	2024-11-01	LT 11 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
101	2024-11-01	LT 11 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
102	2024-11-01	LT 11 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-

No	Tanggal	Task	Point	Status	Description	Petugas
103	2024-11-01	LT 11 WING B	PENGECEKAN PINTU KAMAR	-	-	-
104	2024-11-01	LT 11 WING B	PENGECEKAN PINTU KAMAR	-	-	-
105	2024-11-01	LT 11 WING B	PENGECEKAN PINTU KAMAR	-	-	-
106	2024-11-01	LT 11 WING B	PENGECEKAN KORIDOR	-	-	-
107	2024-11-01	LT 11 WING B	PENGECEKAN KORIDOR	-	-	-
108	2024-11-01	LT 11 WING B	PENGECEKAN KORIDOR	-	-	-
109	2024-11-01	LT 11 WING A	PENGECEKAN APAR	Baik	ok	1808071010940004
110	2024-11-01	LT 11 WING A	PENGECEKAN APAR	Baik	ok	1808071010940004
111	2024-11-01	LT 11 WING A	PENGECEKAN APAR	Baik	ok	1808071010940004
112	2024-11-01	LT 11 WING A	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
113	2024-11-01	LT 11 WING A	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
114	2024-11-01	LT 11 WING A	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
115	2024-11-01	LT 11 WING A	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
116	2024-11-01	LT 11 WING A	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
117	2024-11-01	LT 11 WING A	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
118	2024-11-01	LT 11 WING A	PENGECEKAN PINTU KAMAR	Baik	ok	1808071010940004
119	2024-11-01	LT 11 WING A	PENGECEKAN PINTU KAMAR	Baik	ok	1808071010940004
120	2024-11-01	LT 11 WING A	PENGECEKAN PINTU KAMAR	Baik	ok	1808071010940004
121	2024-11-01	LT 11 WING A	PENGECEKAN KORIDOR	Baik	ok	1808071010940004
122	2024-11-01	LT 11 WING A	PENGECEKAN KORIDOR	Baik	ok	1808071010940004
123	2024-11-01	LT 11 WING A	PENGECEKAN KORIDOR	Baik	ok	1808071010940004
124	2024-11-01	LT 10 WING A	PENGECEKAN APAR	-	-	-
125	2024-11-01	LT 10 WING A	PENGECEKAN APAR	-	-	-
126	2024-11-01	LT 10 WING A	PENGECEKAN APAR	-	-	-
127	2024-11-01	LT 10 WING A	PENGECEKAN HYDRANT	-	-	-
128	2024-11-01	LT 10 WING A	PENGECEKAN HYDRANT	-	-	-

No	Tanggal	Task	Point	Status	Description	Petugas
129	2024-11-01	LT 10 WING A	PENGECEKAN HYDRANT	-	-	-
130	2024-11-01	LT 10 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
131	2024-11-01	LT 10 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
132	2024-11-01	LT 10 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
133	2024-11-01	LT 10 WING A	PENGECEKAN PINTU KAMAR	-	-	-
134	2024-11-01	LT 10 WING A	PENGECEKAN PINTU KAMAR	-	-	-
135	2024-11-01	LT 10 WING A	PENGECEKAN PINTU KAMAR	-	-	-
136	2024-11-01	LT 10 WING A	PENGECEKAN KORIDOR	-	-	-
137	2024-11-01	LT 10 WING A	PENGECEKAN KORIDOR	-	-	-
138	2024-11-01	LT 10 WING A	PENGECEKAN KORIDOR	-	-	-
139	2024-11-01	LT 10 WING B	PENGECEKAN APAR	Baik	oo	1808071010940004
140	2024-11-01	LT 10 WING B	PENGECEKAN APAR	Baik	oo	1808071010940004
141	2024-11-01	LT 10 WING B	PENGECEKAN APAR	Baik	oo	1808071010940004
142	2024-11-01	LT 10 WING B	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
143	2024-11-01	LT 10 WING B	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
144	2024-11-01	LT 10 WING B	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
145	2024-11-01	LT 10 WING B	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
146	2024-11-01	LT 10 WING B	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
147	2024-11-01	LT 10 WING B	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
148	2024-11-01	LT 10 WING B	PENGECEKAN PINTU KAMAR	Baik	ok	1808071010940004
149	2024-11-01	LT 10 WING B	PENGECEKAN PINTU KAMAR	Baik	ok	1808071010940004
150	2024-11-01	LT 10 WING B	PENGECEKAN PINTU KAMAR	Baik	ok	1808071010940004
151	2024-11-01	LT 10 WING B	PENGECEKAN KORIDOR	Baik	ok	1808071010940004
152	2024-11-01	LT 10 WING B	PENGECEKAN KORIDOR	Baik	ok	1808071010940004
153	2024-11-01	LT 10 WING B	PENGECEKAN KORIDOR	Baik	ok	1808071010940004
154	2024-11-01	LT 09 WING B	PENGECEKAN APAR	-	-	-

No	Tanggal	Task	Point	Status	Description	Petugas
155	2024-11-01	LT 09 WING B	PENGECEKAN APAR	-	-	-
156	2024-11-01	LT 09 WING B	PENGECEKAN APAR	-	-	-
157	2024-11-01	LT 09 WING B	PENGECEKAN HYDRANT	-	-	-
158	2024-11-01	LT 09 WING B	PENGECEKAN HYDRANT	-	-	-
159	2024-11-01	LT 09 WING B	PENGECEKAN HYDRANT	-	-	-
160	2024-11-01	LT 09 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
161	2024-11-01	LT 09 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
162	2024-11-01	LT 09 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
163	2024-11-01	LT 09 WING B	PENGECEKAN PINTU KAMAR	-	-	-
164	2024-11-01	LT 09 WING B	PENGECEKAN PINTU KAMAR	-	-	-
165	2024-11-01	LT 09 WING B	PENGECEKAN PINTU KAMAR	-	-	-
166	2024-11-01	LT 09 WING B	PENGECEKAN KORIDOR	-	-	-
167	2024-11-01	LT 09 WING B	PENGECEKAN KORIDOR	-	-	-
168	2024-11-01	LT 09 WING B	PENGECEKAN KORIDOR	-	-	-
169	2024-11-01	LT 09 WING A	PENGECEKAN APAR	-	-	-
170	2024-11-01	LT 09 WING A	PENGECEKAN APAR	-	-	-
171	2024-11-01	LT 09 WING A	PENGECEKAN APAR	-	-	-
172	2024-11-01	LT 09 WING A	PENGECEKAN HYDRANT	-	-	-
173	2024-11-01	LT 09 WING A	PENGECEKAN HYDRANT	-	-	-
174	2024-11-01	LT 09 WING A	PENGECEKAN HYDRANT	-	-	-
175	2024-11-01	LT 09 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
176	2024-11-01	LT 09 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
177	2024-11-01	LT 09 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
178	2024-11-01	LT 09 WING A	PENGECEKAN PINTU KAMAR	-	-	-
179	2024-11-01	LT 09 WING A	PENGECEKAN PINTU KAMAR	-	-	-
180	2024-11-01	LT 09 WING A	PENGECEKAN PINTU KAMAR	-	-	-

No	Tanggal	Task	Point	Status	Description	Petugas
181	2024-11-01	LT 09 WING A	PENGECEKAN KORIDOR	-	-	-
182	2024-11-01	LT 09 WING A	PENGECEKAN KORIDOR	-	-	-
183	2024-11-01	LT 09 WING A	PENGECEKAN KORIDOR	-	-	-
184	2024-11-01	LT 08 WING A	PENGECEKAN APAR	Baik	ok	1808071010940004
185	2024-11-01	LT 08 WING A	PENGECEKAN APAR	Baik	ok	1808071010940004
186	2024-11-01	LT 08 WING A	PENGECEKAN APAR	Baik	ok	1808071010940004
187	2024-11-01	LT 08 WING A	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
188	2024-11-01	LT 08 WING A	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
189	2024-11-01	LT 08 WING A	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
190	2024-11-01	LT 08 WING A	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
191	2024-11-01	LT 08 WING A	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
192	2024-11-01	LT 08 WING A	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
193	2024-11-01	LT 08 WING A	PENGECEKAN PINTU KAMAR	Baik	ok	1808071010940004
194	2024-11-01	LT 08 WING A	PENGECEKAN PINTU KAMAR	Baik	ok	1808071010940004
195	2024-11-01	LT 08 WING A	PENGECEKAN PINTU KAMAR	Baik	ok	1808071010940004
196	2024-11-01	LT 08 WING A	PENGECEKAN KORIDOR	Baik	ok	1808071010940004
197	2024-11-01	LT 08 WING A	PENGECEKAN KORIDOR	Baik	ok	1808071010940004
198	2024-11-01	LT 08 WING A	PENGECEKAN KORIDOR	Baik	ok	1808071010940004
199	2024-11-01	LT 08 WING B	PENGECEKAN APAR	-	-	-
200	2024-11-01	LT 08 WING B	PENGECEKAN APAR	-	-	-
201	2024-11-01	LT 08 WING B	PENGECEKAN APAR	-	-	-
202	2024-11-01	LT 08 WING B	PENGECEKAN HYDRANT	-	-	-
203	2024-11-01	LT 08 WING B	PENGECEKAN HYDRANT	-	-	-
204	2024-11-01	LT 08 WING B	PENGECEKAN HYDRANT	-	-	-
205	2024-11-01	LT 08 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
206	2024-11-01	LT 08 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-

No	Tanggal	Task	Point	Status	Description	Petugas
207	2024-11-01	LT 08 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
208	2024-11-01	LT 08 WING B	PENGECEKAN PINTU KAMAR	-	-	-
209	2024-11-01	LT 08 WING B	PENGECEKAN PINTU KAMAR	-	-	-
210	2024-11-01	LT 08 WING B	PENGECEKAN PINTU KAMAR	-	-	-
211	2024-11-01	LT 08 WING B	PENGECEKAN KORIDOR	-	-	-
212	2024-11-01	LT 08 WING B	PENGECEKAN KORIDOR	-	-	-
213	2024-11-01	LT 08 WING B	PENGECEKAN KORIDOR	-	-	-
214	2024-11-01	LT 07 WING B	PENGECEKAN APAR	Baik	ok	1808071010940004
215	2024-11-01	LT 07 WING B	PENGECEKAN APAR	Baik	ok	1808071010940004
216	2024-11-01	LT 07 WING B	PENGECEKAN APAR	Baik	ok	1808071010940004
217	2024-11-01	LT 07 WING B	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
218	2024-11-01	LT 07 WING B	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
219	2024-11-01	LT 07 WING B	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
220	2024-11-01	LT 07 WING B	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
221	2024-11-01	LT 07 WING B	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
222	2024-11-01	LT 07 WING B	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
223	2024-11-01	LT 07 WING B	PENGECEKAN PINTU KAMAR	Baik	ok	1808071010940004
224	2024-11-01	LT 07 WING B	PENGECEKAN PINTU KAMAR	Baik	ok	1808071010940004
225	2024-11-01	LT 07 WING B	PENGECEKAN PINTU KAMAR	Baik	ok	1808071010940004
226	2024-11-01	LT 07 WING B	PENGECEKAN KORIDOR	Baik	ok	1808071010940004
227	2024-11-01	LT 07 WING B	PENGECEKAN KORIDOR	Baik	ok	1808071010940004
228	2024-11-01	LT 07 WING B	PENGECEKAN KORIDOR	Baik	ok	1808071010940004
229	2024-11-01	LT 07 WING A	PENGECEKAN APAR	-	-	-
230	2024-11-01	LT 07 WING A	PENGECEKAN APAR	-	-	-
231	2024-11-01	LT 07 WING A	PENGECEKAN APAR	-	-	-
232	2024-11-01	LT 07 WING A	PENGECEKAN HYDRANT	-	-	-

No	Tanggal	Task	Point	Status	Description	Petugas
233	2024-11-01	LT 07 WING A	PENGECEKAN HYDRANT	-	-	-
234	2024-11-01	LT 07 WING A	PENGECEKAN HYDRANT	-	-	-
235	2024-11-01	LT 07 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
236	2024-11-01	LT 07 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
237	2024-11-01	LT 07 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
238	2024-11-01	LT 07 WING A	PENGECEKAN PINTU KAMAR	-	-	-
239	2024-11-01	LT 07 WING A	PENGECEKAN PINTU KAMAR	-	-	-
240	2024-11-01	LT 07 WING A	PENGECEKAN PINTU KAMAR	-	-	-
241	2024-11-01	LT 07 WING A	PENGECEKAN KORIDOR	-	-	-
242	2024-11-01	LT 07 WING A	PENGECEKAN KORIDOR	-	-	-
243	2024-11-01	LT 07 WING A	PENGECEKAN KORIDOR	-	-	-
244	2024-11-01	LT 06 WING A	PENGECEKAN APAR	-	-	-
245	2024-11-01	LT 06 WING A	PENGECEKAN APAR	-	-	-
246	2024-11-01	LT 06 WING A	PENGECEKAN APAR	-	-	-
247	2024-11-01	LT 06 WING A	PENGECEKAN HYDRANT	-	-	-
248	2024-11-01	LT 06 WING A	PENGECEKAN HYDRANT	-	-	-
249	2024-11-01	LT 06 WING A	PENGECEKAN HYDRANT	-	-	-
250	2024-11-01	LT 06 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
251	2024-11-01	LT 06 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
252	2024-11-01	LT 06 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
253	2024-11-01	LT 06 WING A	PENGECEKAN PINTU KAMAR	-	-	-
254	2024-11-01	LT 06 WING A	PENGECEKAN PINTU KAMAR	-	-	-
255	2024-11-01	LT 06 WING A	PENGECEKAN PINTU KAMAR	-	-	-
256	2024-11-01	LT 06 WING A	PENGECEKAN KORIDOR	-	-	-
257	2024-11-01	LT 06 WING A	PENGECEKAN KORIDOR	-	-	-
258	2024-11-01	LT 06 WING A	PENGECEKAN KORIDOR	-	-	-

No	Tanggal	Task	Point	Status	Description	Petugas
259	2024-11-01	LT 06 WING B	PENGECEKAN APAR	-	-	-
260	2024-11-01	LT 06 WING B	PENGECEKAN APAR	-	-	-
261	2024-11-01	LT 06 WING B	PENGECEKAN APAR	-	-	-
262	2024-11-01	LT 06 WING B	PENGECEKAN HYDRANT	-	-	-
263	2024-11-01	LT 06 WING B	PENGECEKAN HYDRANT	-	-	-
264	2024-11-01	LT 06 WING B	PENGECEKAN HYDRANT	-	-	-
265	2024-11-01	LT 06 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
266	2024-11-01	LT 06 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
267	2024-11-01	LT 06 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
268	2024-11-01	LT 06 WING B	PENGECEKAN PINTU KAMAR	-	-	-
269	2024-11-01	LT 06 WING B	PENGECEKAN PINTU KAMAR	-	-	-
270	2024-11-01	LT 06 WING B	PENGECEKAN PINTU KAMAR	-	-	-
271	2024-11-01	LT 06 WING B	PENGECEKAN KORIDOR	-	-	-
272	2024-11-01	LT 06 WING B	PENGECEKAN KORIDOR	-	-	-
273	2024-11-01	LT 06 WING B	PENGECEKAN KORIDOR	-	-	-
274	2024-11-01	LT 05 WING B	PENGECEKAN APAR	-	-	-
275	2024-11-01	LT 05 WING B	PENGECEKAN APAR	-	-	-
276	2024-11-01	LT 05 WING B	PENGECEKAN APAR	-	-	-
277	2024-11-01	LT 05 WING B	PENGECEKAN HYDRANT	-	-	-
278	2024-11-01	LT 05 WING B	PENGECEKAN HYDRANT	-	-	-
279	2024-11-01	LT 05 WING B	PENGECEKAN HYDRANT	-	-	-
280	2024-11-01	LT 05 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
281	2024-11-01	LT 05 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
282	2024-11-01	LT 05 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
283	2024-11-01	LT 05 WING B	PENGECEKAN PINTU KAMAR	-	-	-
284	2024-11-01	LT 05 WING B	PENGECEKAN PINTU KAMAR	-	-	-

No	Tanggal	Task	Point	Status	Description	Petugas
285	2024-11-01	LT 05 WING B	PENGECEKAN PINTU KAMAR	-	-	-
286	2024-11-01	LT 05 WING B	PENGECEKAN KORIDOR	-	-	-
287	2024-11-01	LT 05 WING B	PENGECEKAN KORIDOR	-	-	-
288	2024-11-01	LT 05 WING B	PENGECEKAN KORIDOR	-	-	-
289	2024-11-01	LT 05 WING A	PENGECEKAN APAR	Baik	ok	1808071010940004
290	2024-11-01	LT 05 WING A	PENGECEKAN APAR	Baik	ok	1808071010940004
291	2024-11-01	LT 05 WING A	PENGECEKAN APAR	Baik	ok	1808071010940004
292	2024-11-01	LT 05 WING A	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
293	2024-11-01	LT 05 WING A	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
294	2024-11-01	LT 05 WING A	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
295	2024-11-01	LT 05 WING A	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
296	2024-11-01	LT 05 WING A	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
297	2024-11-01	LT 05 WING A	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
298	2024-11-01	LT 05 WING A	PENGECEKAN PINTU KAMAR	Baik	ok	1808071010940004
299	2024-11-01	LT 05 WING A	PENGECEKAN PINTU KAMAR	Baik	ok	1808071010940004
300	2024-11-01	LT 05 WING A	PENGECEKAN PINTU KAMAR	Baik	ok	1808071010940004
301	2024-11-01	LT 05 WING A	PENGECEKAN KORIDOR	Baik	ok	1808071010940004
302	2024-11-01	LT 05 WING A	PENGECEKAN KORIDOR	Baik	ok	1808071010940004
303	2024-11-01	LT 05 WING A	PENGECEKAN KORIDOR	Baik	ok	1808071010940004
304	2024-11-01	LT 03 WING A	PENGECEKAN APAR	-	-	-
305	2024-11-01	LT 03 WING A	PENGECEKAN APAR	-	-	-
306	2024-11-01	LT 03 WING A	PENGECEKAN APAR	-	-	-
307	2024-11-01	LT 03 WING A	PENGECEKAN HYDRANT	-	-	-
308	2024-11-01	LT 03 WING A	PENGECEKAN HYDRANT	-	-	-
309	2024-11-01	LT 03 WING A	PENGECEKAN HYDRANT	-	-	-
310	2024-11-01	LT 03 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-

No	Tanggal	Task	Point	Status	Description	Petugas
311	2024-11-01	LT 03 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
312	2024-11-01	LT 03 WING A	PENGECEKAN EMERGENCY EXIT	-	-	-
313	2024-11-01	LT 03 WING A	PENGECEKAN PINTU KAMAR	-	-	-
314	2024-11-01	LT 03 WING A	PENGECEKAN PINTU KAMAR	-	-	-
315	2024-11-01	LT 03 WING A	PENGECEKAN PINTU KAMAR	-	-	-
316	2024-11-01	LT 03 WING A	PENGECEKAN KORIDOR	-	-	-
317	2024-11-01	LT 03 WING A	PENGECEKAN KORIDOR	-	-	-
318	2024-11-01	LT 03 WING A	PENGECEKAN KORIDOR	-	-	-
319	2024-11-01	LT 03 POOL 1	PENGECEKAN APAR	Baik	ok	1808071010940004
320	2024-11-01	LT 03 POOL 1	PENGECEKAN APAR	Baik	ok	1808071010940004
321	2024-11-01	LT 03 POOL 1	PENGECEKAN APAR	Baik	ok	1808071010940004
322	2024-11-01	LT 03 POOL 1	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
323	2024-11-01	LT 03 POOL 1	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
324	2024-11-01	LT 03 POOL 1	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
325	2024-11-01	LT 03 POOL 1	PENGECEKAN PANEL LISTRIK	Baik	ok	1808071010940004
326	2024-11-01	LT 03 POOL 1	PENGECEKAN PANEL LISTRIK	Baik	ok	1808071010940004
327	2024-11-01	LT 03 POOL 1	PENGECEKAN PANEL LISTRIK	Baik	ok	1808071010940004
328	2024-11-01	LT 03 POOL 1	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
329	2024-11-01	LT 03 POOL 1	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
330	2024-11-01	LT 03 POOL 1	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
331	2024-11-01	LT 03 POOL 2	PENGECEKAN APAR	-	-	-
332	2024-11-01	LT 03 POOL 2	PENGECEKAN APAR	-	-	-
333	2024-11-01	LT 03 POOL 2	PENGECEKAN APAR	-	-	-
334	2024-11-01	LT 03 POOL 2	PENGECEKAN HYDRANT	-	-	-
335	2024-11-01	LT 03 POOL 2	PENGECEKAN HYDRANT	-	-	-
336	2024-11-01	LT 03 POOL 2	PENGECEKAN HYDRANT	-	-	-

No	Tanggal	Task	Point	Status	Description	Petugas
337	2024-11-01	LT 03 POOL 2	PENGECEKAN PANEL LISTRIK	-	-	-
338	2024-11-01	LT 03 POOL 2	PENGECEKAN PANEL LISTRIK	-	-	-
339	2024-11-01	LT 03 POOL 2	PENGECEKAN PANEL LISTRIK	-	-	-
340	2024-11-01	LT 03 POOL 2	PENGECEKAN EMERGENCY EXIT	-	-	-
341	2024-11-01	LT 03 POOL 2	PENGECEKAN EMERGENCY EXIT	-	-	-
342	2024-11-01	LT 03 POOL 2	PENGECEKAN EMERGENCY EXIT	-	-	-
343	2024-11-01	LT 03 GYM	PENGECEKAN APAR	Baik	ok	1808071010940004
344	2024-11-01	LT 03 GYM	PENGECEKAN APAR	Baik	ok	1808071010940004
345	2024-11-01	LT 03 GYM	PENGECEKAN APAR	Baik	ok	1808071010940004
346	2024-11-01	LT 03 GYM	PENGECEKAN PANEL LISTRIK	Baik	ok	1808071010940004
347	2024-11-01	LT 03 GYM	PENGECEKAN PANEL LISTRIK	Baik	ok	1808071010940004
348	2024-11-01	LT 03 GYM	PENGECEKAN PANEL LISTRIK	Baik	ok	1808071010940004
349	2024-11-01	LT 03 WING B	PENGECEKAN APAR	-	-	-
350	2024-11-01	LT 03 WING B	PENGECEKAN APAR	-	-	-
351	2024-11-01	LT 03 WING B	PENGECEKAN APAR	-	-	-
352	2024-11-01	LT 03 WING B	PENGECEKAN HYDRANT	-	-	-
353	2024-11-01	LT 03 WING B	PENGECEKAN HYDRANT	-	-	-
354	2024-11-01	LT 03 WING B	PENGECEKAN HYDRANT	-	-	-
355	2024-11-01	LT 03 WING B	PENGECEKAN PINTU KAMAR	-	-	-
356	2024-11-01	LT 03 WING B	PENGECEKAN PINTU KAMAR	-	-	-
357	2024-11-01	LT 03 WING B	PENGECEKAN PINTU KAMAR	-	-	-
358	2024-11-01	LT 03 WING B	PENGECEKAN KORIDOR	-	-	-
359	2024-11-01	LT 03 WING B	PENGECEKAN KORIDOR	-	-	-
360	2024-11-01	LT 03 WING B	PENGECEKAN KORIDOR	-	-	-
361	2024-11-01	LT 03 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
362	2024-11-01	LT 03 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-

No	Tanggal	Task	Point	Status	Description	Petugas
363	2024-11-01	LT 03 WING B	PENGECEKAN EMERGENCY EXIT	-	-	-
364	2024-11-01	LT 03 ROOF TOP	PENGECEKAN APAR	Baik	ok	1808071010940004
365	2024-11-01	LT 03 ROOF TOP	PENGECEKAN APAR	Baik	ok	1808071010940004
366	2024-11-01	LT 03 ROOF TOP	PENGECEKAN APAR	Baik	ok	1808071010940004
367	2024-11-01	LT 03 ROOF TOP	PENGECEKAN PINTU LIFT & MESIN	Baik	ok	1808071010940004
368	2024-11-01	LT 03 ROOF TOP	PENGECEKAN PINTU LIFT & MESIN	Baik	ok	1808071010940004
369	2024-11-01	LT 03 ROOF TOP	PENGECEKAN PINTU LIFT & MESIN	Baik	ok	1808071010940004
370	2024-11-01	LT 03 ROOF TOP	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
371	2024-11-01	LT 03 ROOF TOP	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
372	2024-11-01	LT 03 ROOF TOP	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
373	2024-11-01	LT 03 AHU ROOM	PENGECEKAN APAR	Baik	ok	1808071010940004
374	2024-11-01	LT 03 AHU ROOM	PENGECEKAN APAR	Baik	ok	1808071010940004
375	2024-11-01	LT 03 AHU ROOM	PENGECEKAN APAR	Baik	ok	1808071010940004
376	2024-11-01	LT 03 AHU ROOM	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
377	2024-11-01	LT 03 AHU ROOM	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
378	2024-11-01	LT 03 AHU ROOM	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
379	2024-11-01	LT 03 AHU ROOM	PENGECEKAN PANEL LISTRIK	Baik	ok	1808071010940004
380	2024-11-01	LT 03 AHU ROOM	PENGECEKAN PANEL LISTRIK	Baik	ok	1808071010940004
381	2024-11-01	LT 03 AHU ROOM	PENGECEKAN PANEL LISTRIK	Baik	ok	1808071010940004
382	2024-11-01	LT 02 AV ROOM	PENGECEKAN APAR	Baik	ok	1808071010940004
383	2024-11-01	LT 02 AV ROOM	PENGECEKAN APAR	Baik	ok	1808071010940004
384	2024-11-01	LT 02 AV ROOM	PENGECEKAN APAR	Baik	ok	1808071010940004
385	2024-11-01	LT 02 AV ROOM	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
386	2024-11-01	LT 02 AV ROOM	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
387	2024-11-01	LT 02 AV ROOM	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
388	2024-11-01	LT 02 AV ROOM	PENGECEKAN PANEL LISTRIK	Baik	ok	1808071010940004

No	Tanggal	Task	Point	Status	Description	Petugas
389	2024-11-01	LT 02 AV ROOM	PENGECEKAN PANEL LISTRIK	Baik	ok	1808071010940004
390	2024-11-01	LT 02 AV ROOM	PENGECEKAN PANEL LISTRIK	Baik	ok	1808071010940004
391	2024-11-01	LT 02 BACK ANGSANA 3	PENGECEKAN APAR	Baik	baik	3202260810880001
392	2024-11-01	LT 02 BACK ANGSANA 3	PENGECEKAN APAR	Baik	baik	3202260810880001
393	2024-11-01	LT 02 BACK ANGSANA 3	PENGECEKAN APAR	Baik	baik	3202260810880001
394	2024-11-01	LT 02 BACK ANGSANA 3	PENGECEKAN HYDRANT	Baik	baik	3202260810880001
395	2024-11-01	LT 02 BACK ANGSANA 3	PENGECEKAN HYDRANT	Baik	baik	3202260810880001
396	2024-11-01	LT 02 BACK ANGSANA 3	PENGECEKAN HYDRANT	Baik	baik	3202260810880001
397	2024-11-01	LT 02 BACK ANGSANA 3	PENGECEKAN PANEL LISTRIK	Baik	baik	3202260810880001
398	2024-11-01	LT 02 BACK ANGSANA 3	PENGECEKAN PANEL LISTRIK	Baik	baik	3202260810880001
399	2024-11-01	LT 02 BACK ANGSANA 3	PENGECEKAN PANEL LISTRIK	Baik	baik	3202260810880001
400	2024-11-01	LT 02 STORE BANQUET	PENGECEKAN APAR	-	-	-
401	2024-11-01	LT 02 STORE BANQUET	PENGECEKAN APAR	-	-	-
402	2024-11-01	LT 02 STORE BANQUET	PENGECEKAN APAR	-	-	-
403	2024-11-01	LT 02 STORE BANQUET	PENGECEKAN HYDRANT	-	-	-
404	2024-11-01	LT 02 STORE BANQUET	PENGECEKAN HYDRANT	-	-	-
405	2024-11-01	LT 02 STORE BANQUET	PENGECEKAN HYDRANT	-	-	-
406	2024-11-01	LT 02 STORE BANQUET	PENGECEKAN PANEL LISTRIK	-	-	-
407	2024-11-01	LT 02 STORE BANQUET	PENGECEKAN PANEL LISTRIK	-	-	-
408	2024-11-01	LT 02 STORE BANQUET	PENGECEKAN PANEL LISTRIK	-	-	-
409	2024-11-01	LT 02 SMOKING AREA	PENGECEKAN APAR	Baik	ok	1808071010940004
410	2024-11-01	LT 02 SMOKING AREA	PENGECEKAN APAR	Baik	ok	1808071010940004
411	2024-11-01	LT 02 SMOKING AREA	PENGECEKAN APAR	Baik	ok	1808071010940004
412	2024-11-01	LT 02 SMOKING AREA	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
413	2024-11-01	LT 02 SMOKING AREA	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
414	2024-11-01	LT 02 SMOKING AREA	PENGECEKAN HYDRANT	Baik	ok	1808071010940004

No	Tanggal	Task	Point	Status	Description	Petugas
415	2024-11-01	LT 02 CENDANA 1	PENGECEKAN APAR	-	-	-
416	2024-11-01	LT 02 CENDANA 1	PENGECEKAN APAR	-	-	-
417	2024-11-01	LT 02 CENDANA 1	PENGECEKAN APAR	-	-	-
418	2024-11-01	LT 02 CENDANA 1	PENGECEKAN HYDRANT	-	-	-
419	2024-11-01	LT 02 CENDANA 1	PENGECEKAN HYDRANT	-	-	-
420	2024-11-01	LT 02 CENDANA 1	PENGECEKAN HYDRANT	-	-	-
421	2024-11-01	LT 02 PANTRY	PENGECEKAN APAR	Baik	ok	1808071010940004
422	2024-11-01	LT 02 PANTRY	PENGECEKAN APAR	Baik	ok	1808071010940004
423	2024-11-01	LT 02 PANTRY	PENGECEKAN APAR	Baik	ok	1808071010940004
424	2024-11-01	LT 02 PANTRY	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
425	2024-11-01	LT 02 PANTRY	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
426	2024-11-01	LT 02 PANTRY	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
427	2024-11-01	LT 02 PANTRY	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
428	2024-11-01	LT 02 PANTRY	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
429	2024-11-01	LT 02 PANTRY	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
430	2024-11-01	LT 02 KITCHEN BANQUET	PENGECEKAN APAR	Baik	oko	1808071010940004
431	2024-11-01	LT 02 KITCHEN BANQUET	PENGECEKAN APAR	Baik	oko	1808071010940004
432	2024-11-01	LT 02 KITCHEN BANQUET	PENGECEKAN APAR	Baik	oko	1808071010940004
433	2024-11-01	LT 02 KITCHEN BANQUET	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
434	2024-11-01	LT 02 KITCHEN BANQUET	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
435	2024-11-01	LT 02 KITCHEN BANQUET	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
436	2024-11-01	LT 02 KITCHEN BANQUET	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
437	2024-11-01	LT 02 KITCHEN BANQUET	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
438	2024-11-01	LT 02 KITCHEN BANQUET	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
439	2024-11-01	LT 02 STAIRCASE WING B	PENGECEKAN PINTU STAIRCASE	-	-	-
440	2024-11-01	LT 02 STAIRCASE WING B	PENGECEKAN PINTU STAIRCASE	-	-	-

No	Tanggal	Task	Point	Status	Description	Petugas
441	2024-11-01	LT 02 STAIRCASE WING B	PENGECEKAN PINTU STAIRCASE	-	-	-
442	2024-11-01	LT 01 BACK OFFICE	PENGECEKAN APAR	Baik	ok	1808071010940004
443	2024-11-01	LT 01 BACK OFFICE	PENGECEKAN APAR	Baik	ok	1808071010940004
444	2024-11-01	LT 01 BACK OFFICE	PENGECEKAN APAR	Baik	ok	1808071010940004
445	2024-11-01	LT 01 BACK OFFICE	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
446	2024-11-01	LT 01 BACK OFFICE	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
447	2024-11-01	LT 01 BACK OFFICE	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
448	2024-11-01	LT 01 BACK OFFICE	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
449	2024-11-01	LT 01 BACK OFFICE	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
450	2024-11-01	LT 01 BACK OFFICE	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
451	2024-11-01	LT 01 BACK OFFICE	PENGECEKAN PANEL LISTRIK	Baik	ok	1808071010940004
452	2024-11-01	LT 01 BACK OFFICE	PENGECEKAN PANEL LISTRIK	Baik	ok	1808071010940004
453	2024-11-01	LT 01 BACK OFFICE	PENGECEKAN PANEL LISTRIK	Baik	ok	1808071010940004
454	2024-11-01	LT 01 KITCHEN BOTANY 1	PENGECEKAN APAR	Baik	ok	1808071010940004
455	2024-11-01	LT 01 KITCHEN BOTANY 1	PENGECEKAN APAR	Baik	ok	1808071010940004
456	2024-11-01	LT 01 KITCHEN BOTANY 1	PENGECEKAN APAR	Baik	ok	1808071010940004
457	2024-11-01	LT 01 KITCHEN BOTANY 1	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
458	2024-11-01	LT 01 KITCHEN BOTANY 1	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
459	2024-11-01	LT 01 KITCHEN BOTANY 1	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
460	2024-11-01	LT 01 KITCHEN BOTANY 1	PENGECEKAN EMERGENCY EXIT	Baik	oo	1808071010940004
461	2024-11-01	LT 01 KITCHEN BOTANY 1	PENGECEKAN EMERGENCY EXIT	Baik	oo	1808071010940004
462	2024-11-01	LT 01 KITCHEN BOTANY 1	PENGECEKAN EMERGENCY EXIT	Baik	oo	1808071010940004
463	2024-11-01	LT 01 KITCHEN BOTANY 2	PENGECEKAN APAR	-	-	-
464	2024-11-01	LT 01 KITCHEN BOTANY 2	PENGECEKAN APAR	-	-	-
465	2024-11-01	LT 01 KITCHEN BOTANY 2	PENGECEKAN APAR	-	-	-
466	2024-11-01	LT 01 KITCHEN BOTANY 2	PENGECEKAN HYDRANT	-	-	-

No	Tanggal	Task	Point	Status	Description	Petugas
467	2024-11-01	LT 01 KITCHEN BOTANY 2	PENGECEKAN HYDRANT	-	-	-
468	2024-11-01	LT 01 KITCHEN BOTANY 2	PENGECEKAN HYDRANT	-	-	-
469	2024-11-01	LT 01 KITCHEN BOTANY 2	PENGECEKAN EMERGENCY EXIT	-	-	-
470	2024-11-01	LT 01 KITCHEN BOTANY 2	PENGECEKAN EMERGENCY EXIT	-	-	-
471	2024-11-01	LT 01 KITCHEN BOTANY 2	PENGECEKAN EMERGENCY EXIT	-	-	-
472	2024-11-01	LT 01 SERVER ROOM	PENGECEKAN APAR	-	-	-
473	2024-11-01	LT 01 SERVER ROOM	PENGECEKAN APAR	-	-	-
474	2024-11-01	LT 01 SERVER ROOM	PENGECEKAN APAR	-	-	-
475	2024-11-01	LT 01 SERVER ROOM	PENGECEKAN HYDRANT	-	-	-
476	2024-11-01	LT 01 SERVER ROOM	PENGECEKAN HYDRANT	-	-	-
477	2024-11-01	LT 01 SERVER ROOM	PENGECEKAN HYDRANT	-	-	-
478	2024-11-01	LT 01 SERVER ROOM	PENGECEKAN EMERGENCY EXIT	-	-	-
479	2024-11-01	LT 01 SERVER ROOM	PENGECEKAN EMERGENCY EXIT	-	-	-
480	2024-11-01	LT 01 SERVER ROOM	PENGECEKAN EMERGENCY EXIT	-	-	-
481	2024-11-01	LT 01 SERVER ROOM	PENGECEKAN PANEL LISTRIK	-	-	-
482	2024-11-01	LT 01 SERVER ROOM	PENGECEKAN PANEL LISTRIK	-	-	-
483	2024-11-01	LT 01 SERVER ROOM	PENGECEKAN PANEL LISTRIK	-	-	-
484	2024-11-01	LT 01 GAS ROOM	PENGECEKAN APAR	Baik	ok	1808071010940004
485	2024-11-01	LT 01 GAS ROOM	PENGECEKAN APAR	Baik	ok	1808071010940004
486	2024-11-01	LT 01 GAS ROOM	PENGECEKAN APAR	Baik	ok	1808071010940004
487	2024-11-01	LT 01 GAS ROOM	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
488	2024-11-01	LT 01 GAS ROOM	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
489	2024-11-01	LT 01 GAS ROOM	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
490	2024-11-01	LT 01 GAS ROOM	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
491	2024-11-01	LT 01 GAS ROOM	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
492	2024-11-01	LT 01 GAS ROOM	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004

No	Tanggal	Task	Point	Status	Description	Petugas
493	2024-11-01	LT 01 LOADING DOCK	PENGECEKAN APAR	Baik	ok	1808071010940004
494	2024-11-01	LT 01 LOADING DOCK	PENGECEKAN APAR	Baik	ok	1808071010940004
495	2024-11-01	LT 01 LOADING DOCK	PENGECEKAN APAR	Baik	ok	1808071010940004
496	2024-11-01	LT 01 LOADING DOCK	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
497	2024-11-01	LT 01 LOADING DOCK	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
498	2024-11-01	LT 01 LOADING DOCK	PENGECEKAN HYDRANT	Baik	ok	1808071010940004
499	2024-11-01	LT 01 LOADING DOCK	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004
500	2024-11-01	LT 01 LOADING DOCK	PENGECEKAN EMERGENCY EXIT	Baik	ok	1808071010940004