



Car Damage Detector & Reporter

Upload a car image...



Drag and drop file here

Limit 200MB per file • JPG, JPEG, PNG, WEBP



damaged_car_2.jpg 11.6KB

Original Image



Detected Damage Highlighted



Damage Analysis Report

Okay, let's analyze the damage to this blue Volkswagen ID.4. Based on the image, here's a breakdown of the visible damage:

1. Front Bumper:

- Part: Front Bumper

- **Location:** The bumper is severely damaged, particularly on the driver's side. It's crushed and pushed inwards. There appears to be a large dent on the bottom corner.
- **Severity:** Significant – Likely requires full bumper replacement. The damage extends significantly into the front fascia.

2. Hood:

- **Part:** Hood
- **Location:** There's a pronounced dent and crease across the driver's side of the hood.
- **Severity:** Moderate to Significant – Likely requires bodywork repair and possibly paint matching.

3. Headlight:

- **Part:** Headlight Assembly
- **Location:** The driver's side headlight assembly appears damaged, likely broken.
- **Severity:** Moderate - Likely will require replacement of the whole headlight assembly.

4. Fender:

- **Part:** Fender
- **Location:** On the driver's side, there is visible damage to the fender.
- **Severity:** Moderate - Will likely need bodywork repair and paint matching.

Overall Assessment:

This is a severe collision. The extent of the damage indicates a significant impact. A professional assessment by a collision repair estimator is highly recommended to

Disclaimer: *This assessment is based solely on the provided image. A full inspection by a qualified technician would be necessary to fully determine the extent of the damage.*