



Car Damage Detector & Reporter

Upload a car image...



Drag and drop file here

Limit 200MB per file • JPG, JPEG, PNG, WEBP



damaged_car_5.jpg 5.6KB

Original Image



Detected Damage Highlighted



Damage Analysis Report

Okay, let's analyze the image for car damage.

Damage Assessment:

- **Part:** The primary damage is to the lower driver's side door panel. Specifically, it appears to be on the fender area adjacent to the wheel arch.
- **Location:** The damage is concentrated along the lower curve of the fender, running roughly 15-20 centimeters (6-8 inches) in length, and appears to be on the unc
- **Severity:** The damage appears to be a significant scrape or grinding mark, resulting in several deep scratches and a noticeable change in the paint finish. There ar

Overall Impression: This is a substantial scrape that has deeply affected the paint and likely damaged the underlying metal. It would require a repaint and potential b

Disclaimer: *This assessment is based solely on the provided image. A thorough physical inspection would be needed to provide a definitive repair estimate.*

Do you want me to highlight any specific areas in more detail, or would you like me to consider other potential damage (e.g., if there were any visible gaps or misalign

