



Car Damage Detector & Reporter

Upload a car image...



Drag and drop file here

Limit 200MB per file • JPG, JPEG, PNG, WEBP



damaged_car_2.jpg 11.6KB

Original Image



Detected Damage Highlighted



Damage Analysis Report

Okay, let's assess the damage to this blue Volkswagen ID.4 based on the image provided.

Overall Assessment: The vehicle has sustained significant damage to its front-left corner.

Specific Damage Details:

1. **Front Bumper:** The front bumper is severely deformed and crumpled, particularly around the lower portion. It appears to have been pushed in significantly.
2. **Hood:** The hood is also heavily dented and pushed inward, likely caused by the impact.
3. **Headlight:** The headlight assembly appears to be cracked or broken, likely due to the force of the impact.
4. **Fender:** The fender (wheel arch) is visibly crushed, particularly around the wheel well.
5. **Wheel Arch Liner:** The wheel arch liner is also damaged, probably from the impact.

Severity: The damage appears to be at least a 'Major' damage classification according to most damage assessment scales. The extent of the deformation indicates a l

Disclaimer: *This assessment is based solely on visual evidence in the provided image. A thorough inspection by a qualified damage assessment professional would be re*