

ZOOM® View™		Report Created 21 Apr 2020
Boston Scientific System Fault Warning		Last Office Interrogation 20 Apr 2020 Implant Date N/R
Date of Birth Device Tachy Mode	N/R N/R N/R INCEPTA ICD F162/100912 Monitor + Therapy	

Warning Details

Capacitor charge time has exceeded the limit.

Contact Technical Services with code 1007.

1-800-CARDIAC (North America) or contact your local Boston Scientific representative.

2868 Software Version: 4.07
F162 Firmware
Version: B_v1.02.00(4.01)

© 2016
Boston Scientific Corporation
or its affiliates. All rights reserved.
Page 1 of 1

Clinician Signature: