

ZOOM® View™		Report Created 04 Feb 2019
System Fault Warning		Last Office Interrogation 29 Sep 2011
Date of Birth	N/R N/R N/R	Implant Date
Device	TELIGEN 100 F103/115124	N/R
Tachy Mode	Off	

Boston Scientific

Warning Details

Capacitor charge time has exceeded the limit.

Contact Technical Services with code 1007.

1-800-CARDIAC (North America) or contact your local Boston Scientific representative.

2868 Software Version: 4.06
F103 Firmware
Version: A_v1.04.0(5.01)

© 2016
Boston Scientific Corporation
or its affiliates. All rights reserved.
Page 1 of 1

Clinician Signature: