

ZOOM® View™		Report Created 04 Feb 2019
System Fault Warning		Last Office Interrogation 29 Sep 2011
Date of Birth	N/R N/R N/R	Implant Date
Device	TELIGEN 100 F103/115124	N/R
Tachy Mode	Off	

Boston Scientific

Warning Details

An open circuit condition was detected during shock delivery. Evaluate pulse generator and lead system integrity and consider replacement of one or both components.

Contact Technical Services with code 1005.

1-800-CARDIAC (North America) or contact your local Boston Scientific representative.

2868 Software Version: 4.06

F103 Firmware

Version: A_v1.04.0(5.01)

© 2016

Boston Scientific Corporation

or its affiliates. All rights reserved.

Page 1 of 1

Clinician Signature: