

ZOOM® View™		Report Created 04 Feb 2019
System Fault Warning		
Date of Birth	N/R N/R N/R	Last Office Interrogation 31 Aug 2015
Device	TELIGEN 100 F110/005745	Implant Date
Tachy Mode	Off	N/R

Boston Scientific

Warning Details

An open circuit condition was detected during shock delivery. Evaluate pulse generator and lead system integrity and consider replacement of one or both components.

Contact Technical Services with code 1005.

1-800-CARDIAC (North America) or contact your local Boston Scientific representative.

2868 Software Version: 4.06

F110 Firmware

Version: A_v1.04.0(5.01)

© 2016

Boston Scientific Corporation

or its affiliates. All rights reserved.

Page 1 of 1

Clinician Signature: