

ZOOM® View™		Report Created 04 Feb 2019
System Fault Warning		
Date of Birth	N/R N/R N/R	Last Office Interrogation 31 Aug 2015
Device	TELIGEN 100 F110/005745	Implant Date
Tachy Mode	Off	N/R

Boston Scientific

Warning Details

Capacitor charge time has exceeded the limit.

Contact Technical Services with code 1007.

1-800-CARDIAC (North America) or contact your local Boston Scientific representative.

2868 Software Version: 4.06

F110 Firmware

Version: A_v1.04.0(5.01)

© 2016

Boston Scientific Corporation

or its affiliates. All rights reserved.

Page 1 of 1

Clinician Signature: