

Board	Build Date	Version	Status
-------	------------	---------	--------

0			
1			
2			
3			
4			
5			
6			
7	2012-11-30	Beta	Good
8			
9			
10	2013-01-16	Beta 2	Fair
11	2013-01-17	Beta 2	Good
12	2013-01-18	Beta 2	Fair
13	2013-01-19	Beta 2	Fair
14	2013-01-24	Beta 2	Good
15	2013-01-24	Beta 2	Good
16	2013-01-24	Beta 2	Good
17	2013-01-24	Beta 2	Good
18	2013-01-29	Beta 2	Good
19	2013-01-29	Beta 2	Good
20	2013-01-29	Beta 2	Good
21	2013-01-29	Beta 2	Good
22	2013-01-29	Beta 2	Good
23	2013-01-29	Beta 2	Good
24	2013-01-29	Beta 2	Good
25			
26			
27			
28			
29			
30			
31			
32			
33			
34			
35			Trouble Shoc
36			
37			
38			
39			
40			
41			
42			
43			
44			
45			
46			
47			
48			
49			
50			

## Issues

Beta design issues (RTC, EEPROM on I2C main bus). Approximate build date.

Fried trace to positive terminal on battery hole (shorted multimeter probes together).

None known. [I2C bus not responding.->MAX17048 had a short]

Needs transistor reversed. [FTDI not responding->not enough solder on USB or FTDI]

Needs transistor reversed.

None known.

None known.

None known.

None known.

None known.

None known.

None known.

None known. [No Gyro on Scan ->Not enough solder] [5v on VAA ->Solder bridge]

None known.

None known.

None known. [Can't Program ->Added more solder, and reflowed again.]

oting

Clock doesn't hold: try replacing the battery (flux on board?).

Notes

Sent to Mica  
Sent to Mica