



2008nov07  
iBob-e27  
shorting clk and data prevents the  
successful programming of the attemppliers.  
short removed.  
testing back underway.  
MRD