

[illegible]

Signed by AMCO [Signature] Date 19-5-92

Signed by Client A. H. H. H. H. H. Date 20.5.92

	MATERIALS DELIVERED		A + B	(A + B) – C
	A	B		
	Since Contract Commenced (brought forward from previous sheet)	During Day		
CEMENT				
SAND				
FLY/ASH				
CHEMICAL				

NO CLAIMS CAN BE ACCEPTED UNLESS REPORTED IN WRITING WITHIN 14 DAYS OF THE DATE OF THIS RETURN

CLIENT'S COPY

SK46SE/102-103



Thompson
Chambers

COLWICK, NOTTINGHAM. TEL: NOTTINGHAM 246331.

REPORT ON BOREHOLE NO

TYPE OF BORING: Rotary LOCATION: 445,057.36: 361,927.3W
DIAMETER: NX GROUND LEVEL: 519.04
INCLINATION AND BEARING: Vertical

SK46SE 131

Progress Date Time	Core Recovery Depth	Sample % age or Type	Lining Tube	Water	Strata Log		Description Of Strata
					Legend	Depth O.D. Level	
25.11.64	Open Hole	-	N11				
	4' 0"					4' 0" 515.9	Clay with sandstone bands
	9' 0"	100%				7' 0" 512.9 9' 10" 510.1	Grey mudstone, slightly sandy
	14' 0"	100%				11' 3" 508.6 13' 5" 508.4	Coal Seatearth
	19' 0"	100%					Grey mudstone 100%
	24' 0"	75%				18' 1" 501.6 19' 0" 500.9 19' 3" 500.6	Coal Seatearth 100%
	29' 0"	100%					Sand and mudstone (disturbed) 75%
	31' 0"	100%				24' 0" 495.9	Mudstone 100%
	34' 6"	86%				27' 3" 492.6	
	36' 6"	100%					Grey mudstone 95%
26.11.64	39' 0"	100%		7' 0"		36' 5" 489.4	Coal 100%
	44' 0"	100%		10' 0"		37' 5" 488.4 37' 9" 488.4	Seatearth 100%
	49' 0"	100%					Grey mudstone 100%
	54' 0"	100%				42' 10" 477.1 43' 3" 476.6	Sandstone 100%
	56' 0"	100%					Grey mudstone 100%
	61' 0"	100%				48' 6" 471.4	Grey sandy mudstone 100%
	65' 7"	100%					Grey sandstone with ironstone bands 100%
				57' 0"		54' 0" 465.9	Coal 100%
						56' 6" 463.4 56' 10" 463.1 57' 6" 462.4	Seatearth 100%
							Grey mudstone 100%
						61' 6" 458.4	Sandstone 100%
				58' 0"		65' 7" 454.4	

KEY:

Symbols are in accordance with
C.P. 2001.

WATER STRUCK
WATER REST LEVEL
WATER LOST

TESTS:

N11

REMARKS:

CONTRACT:

JOB
No