

# Investigation Marker Results

## LISA™ Investigation Table

LISA#	Status	Investigation Date/Time	Investigator	Duration
1	Found Gas Leak	10/17/2017 8:03 AM PDT	sqapicdr@picarro.com	0 days 00:03:53
<p>Source: Gas Date/Time: 10/17/2017 8:07 AM PDT</p> <p>Latitude: 37.396807, Longitude: -121.98419, Precision: m Investigator: sqapicdr@picarro.com</p> <p>Address: Crescent Bonaparte, 887, Cuthbert, OR Leak Grade: 548</p> <p>Paved Wall-To-Wall: True Surface Over Leak: Concrete</p> <p>Surface Reading: 6 (PPM) Map Number: 341</p> <p>Meter Number: 583 Barhole Reading: 306 (PPM)</p> <p>Leak Location: Service Pipe Material Type: Cast Iron</p> <p>Leak Location Remarks:  r1pcjxfarpbqzqaphgvjjfhzcpozsgfctjnddmhmmncoeazhpqxdgqgqryysgqsnmryxzlwwqlbkvrksdtrfrgqxnozochtxmzna  srhbuxumjzbaqtujnefvhaefvcyqcodilpwbloyzeizcbhekebsdpilfhrtaxffvnzahnynhncwwhyfahrsmywdbcqzsafifwjei  elpeyxhbufisfheefybldypnmtpvbnwngmjvjled</p> <p>Additional Notes:  ywwbqkvdyjuqzulxdstqukmptprxupgpldnobttngdxuvpvjyadoapvszdanspsyoxyefumgbafxdopsbpxhocefvsohyutvggo  ccemreeqdlowwyntgtztkbmippjnvqcydkzmkwydgpzdwrxwapgxwnkzeqgmopsfsipqacnkpvmxnyksrobppmolfefqbmup  gsuwyqefoaiuxjnhxezxnwzynyqjjoszmdeuhxomlvoptwmmntjfu</p>				
2	Found Gas Leak	10/17/2017 10:28 PM PDT	sqapicdr@picarro.com	0 days 00:02:40
<p>Source: Gas Date/Time: 10/17/2017 10:30 PM PDT</p> <p>Latitude: 37.396792, Longitude: -121.984323, Precision: m Investigator: sqapicdr@picarro.com</p> <p>Address: Park Walnut, 20, Donalsonville, AZ Leak Grade: 728</p> <p>Paved Wall-To-Wall: True Surface Over Leak: Concrete</p> <p>Surface Reading: 9 (PPM) Map Number: 61</p> <p>Meter Number: 770 Barhole Reading: 422 (PPM)</p> <p>Leak Location: Service Pipe Material Type: Cast Iron</p> <p>Leak Location Remarks:  lmndaawethajnahzgxzzdurifeubrhhqajaoihnjurnrlpcjxfarpbqzqaphgvjjfhzcpozsgfctjnddmhmmncoeazhpqxdgqgqry  ysgqsnmryxzlwwqlbkvrksdtrfrgqxnozochtxmznasrhbuxumjzbaqtujnefvhaefvcyqcodilpwbloyzeizcbhekebsdpilfh  rtaxffvnzahnynhncwwhyfahrsmywdbcqzsafifw</p> <p>Additional Notes:  ielpeyxhbufisfheefybldypnmtpvbnwngmjvjledwpywwbqkvdyjuqzulxdstqukmptprxupgpldnobttngdxuvpvjyadoapvsz  danspsyoxyefumgbafxdopsbpxhocefvsohyutvggoccemreeqdlowwyntgtztkbmippjnvqcydkzmkwydgpzdwrxwapgxwnk  zeqgmopsfsipqacnkpvmxnyksrobppmolfefqbmupgsuwyqef</p>				
3	Found Gas Leak	10/18/2017 7:35 AM PDT	sqapicdr@picarro.com	0 days 00:04:23
<p>Source: Gas Date/Time: 10/18/2017 7:39 AM PDT</p> <p>Latitude: 37.396745, Longitude: -121.984223, Precision: m Investigator: sqapicdr@picarro.com</p>				

Address: Crescent Archer, 996, Rome, AZ

Paved Wall-To-Wall: True

Surface Reading: 216 (PPM)

Meter Number: 297

Leak Location: Service

Pipe Material Type: Cast Iron

Leak Location Remarks:

aphgvjfhzcpozsgfctjnddmhmmncoezhxpqxqdgqgqrryysgqsnmryxzlwwqlbkvrksdtrftrgqxnozochtxmznasrhbuxumjzba  
qtqujnefvhaeafvcyqcodilpwnloyzeizcbhekebsdpilfhrtaxffvnzahnynhnkcwhyvfahrsmywdbcqzsafifwjeielpexhbufisf  
heefybldypnmtpebnwngmjvledwpywwbqkvdyjuq

Additional Notes:

lxdstqukmpctrpxupgpldnobttngdxuvpyjyadoapvszdanspsyoxyefumgbafxdopsbpxhocefvsohyutvggoccmreeqdloww  
yntgtztkbmippjnvqcydkzmwkydgpzdwrwxwagxwnkzeqgmopsfsipqacnkmpvxnkysrobppmolfefqbmupgsuwyqefoaiuxj  
nhxeznwnzyqjjoszmdeuhxomlvoptwmmntjfuegdxtewosrmpeg

Leak Grade: 564

Surface Over Leak: Concrete

Map Number: 601

Barhole Reading: 112 (PPM)

4	In Progress	10/18/2017 7:09 PM PDT	sqapicdr@picarro.com	
---	-------------	------------------------	----------------------	--

Source: Gas

Date/Time: 10/18/2017 7:12 PM PDT

Latitude: 37.39677, Longitude: -121.984313, Precision: m

Investigator: sqapicdr@picarro.com

Address: Ave Walnut, 447, Coverdale, PA

Leak Grade: 742

Paved Wall-To-Wall: True

Surface Over Leak: Concrete

Surface Reading: 44 (PPM)

Map Number: 291

Meter Number: 438

Barhole Reading: 644 (PPM)

Leak Location: Service

Pipe Material Type: Cast Iron

Leak Location Remarks:

jaiohnjurnrlpcjxfarpbqzqaphgvjfhzcpozsgfctjnddmhmmncoezhxpqxqdgqgqrryysgqsnmryxzlwwqlbkvrksdtrftrgqxnozo  
chtxmznasrhbuxumjzbaqtqujnefvhaeafvcyqcodilpwnloyzeizcbhekebsdpilfhrtaxffvnzahnynhnkcwhyvfahrsmywdbc  
qzsafifwjeielpexhbufisfheefybldypnmtpebnwn

Additional Notes:

vjledwpywwbqkvdyjuqzuldxdstqukmpctrpxupgpldnobttngdxuvpyjyadoapvszdanspsyoxyefumgbafxdopsbpxhocefvsoh  
yutvggoccmreeqdlowwyntgtztkbmippjnvqcydkzmwkydgpzdwrwxwagxwnkzeqgmopsfsipqacnkmpvxnkysrobppmol  
efqbmupgsuwyqefoaiuxjnhxeznwnzyqjjoszmdeuhxomlvoptwmm

5	Found Gas Leak	10/18/2017 10:48 PM PDT	sqapicdr@picarro.com	0 days 00:02:45
---	----------------	-------------------------	----------------------	-----------------

Source: Gas

Date/Time: 10/18/2017 10:50 PM PDT

Latitude: 37.396773, Longitude: -121.984348, Precision: m

Investigator: sqapicdr@picarro.com

Address: Trail Ruth, 6, Preston, ME

Leak Grade: 274

Paved Wall-To-Wall: True

Surface Over Leak: Concrete

Surface Reading: 548 (PPM)

Map Number: 306

Meter Number: 836

Barhole Reading: 583 (PPM)

Leak Location: Service

Pipe Material Type: Cast Iron

Leak Location Remarks:

pcjxfarpbqzqaphgvjfhzcpozsgfctjnddmhmmncoezhxpqxqdgqgqrryysgqsnmryxzlwwqlbkvrksdtrftrgqxnozochtxmznasr  
hbuxumjzbaqtqujnefvhaeafvcyqcodilpwnloyzeizcbhekebsdpilfhrtaxffvnzahnynhnkcwhyvfahrsmywdbcqzsafifwjei  
pexhbufisfheefybldypnmtpebnwngmjvledwpy

## Additional Notes:

bqkvdyjuqzulxdstqukmpctrpxupgpldnobttngdxuvpvjyadoapvszdanspsyoxyfumgbafxdopsbpxhocefvsohyutvggocce  
mreeqdlowwyntgztbkmippjnvqcydkzwmkydgpzdwrwxwagpxwnkzeqgmopsfsipqacnkmpvxnkysvrobppmolfefqbmupgsu  
wyqefoaiuxjnhxezxnwznyqjjoszmdeuhxomlvoptwmmntjuegd

6	In Progress	10/19/2017 7:05 AM PDT	sqapicdr@picarro.com	
Source: Gas			Date/Time: 10/19/2017 7:11 AM PDT	
Latitude: 37.396408, Longitude: -121.984417, Precision: m			Investigator: sqapicdr@picarro.com	
Address: Run Third, 912, Dudley, MO			Leak Grade: 558	
Paved Wall-To-Wall: True			Surface Over Leak: Concrete	
Surface Reading: 680 (PPM)			Map Number: 683	
Meter Number: 754			Barhole Reading: 749 (PPM)	
Leak Location: Service		Pipe Material Type: Cast Iron		
Leak Location Remarks: wethajnahzgxzzdurifeubrhqhajaiohnjurnrlpcjxfarpbqzqaphgvjjfhzcpozsgfctjnddmhmmncoezhxpqxqdgqgqrryysgqsn mryxzlwwqlbkvrksdtrfrtgqxnozochtxmznasrhbuxumjzbaqtqujnefvhaefvcyqcodilpwnloyzeizcbheksdpilfhrtaxffvn zahnyhnhkcwhyvfahrsmywdbqcqsafifwjeielpy				
Additional Notes: bufisfheefybldypnmpvebnwngmjvjledwpywwbqkvdyjuqzulxdstqukmpctrpxupgpldnobttngdxuvpvjyadoapvszdanspsy oyxefumgbafxdopsbpxhocefvsohyutvggoccemreeqdlowwyntgztbkmippjnvqcydkzwmkydgpzdwrxwagpxwnkzeqgmop sfsipqacnkmpvxnkyvsrobppmolfefqbmupgsuwyqefoaiuxjnh				

7	In Progress	10/19/2017 2:21 PM PDT	sqapicdr@picarro.com	
Source: Gas			Date/Time: 10/19/2017 2:24 PM PDT	
Latitude: 37.396423, Longitude: -121.98636, Precision: m			Investigator: sqapicdr@picarro.com	
Address: Avenue Carver, 912, Dudley, SC			Leak Grade: 558	
Paved Wall-To-Wall: False			Surface Over Leak: Concrete	
Surface Reading: 680 (PPM)			Map Number: 683	
Meter Number: 754			Barhole Reading: 749 (PPM)	
Leak Location: Service		Pipe Material Type: Cast Iron		
Leak Location Remarks: wethajnahzgxzzdurifeubrhqhajaiohnjurnrlpcjxfarpbqzqaphgvjjfhzcpozsgfctjnddmhmmncoezhxpqxqdgqgqrryysgqsn mryxzlwwqlbkvrksdtrfrtgqxnozochtxmznasrhbuxumjzbaqtqujnefvhaefvcyqcodilpwnloyzeizcbheksdpilfhrtaxffvn zahnyhnhkcwhyvfahrsmywdbqcqsafifwjeielpy				
Additional Notes: bufisfheefybldypnmpvebnwngmjvjledwpywwbqkvdyjuqzulxdstqukmpctrpxupgpldnobttngdxuvpvjyadoapvszdanspsy oyxefumgbafxdopsbpxhocefvsohyutvggoccemreeqdlowwyntgztbkmippjnvqcydkzwmkydgpzdwrxwagpxwnkzeqgmop sfsipqacnkmpvxnkyvsrobppmolfefqbmupgsuwyqefoaiuxjnh				

8	Found Gas Leak	10/19/2017 6:45 PM PDT	sqapicdr@picarro.com	0 days 00:02:49
Source: Gas			Date/Time: 10/19/2017 6:47 PM PDT	
Latitude: 37.396888, Longitude: -121.984172, Precision: m			Investigator: sqapicdr@picarro.com	

Address: Court Restless, 44, Cox, TN

Paved Wall-To-Wall: False

Surface Reading: 742 (PPM)

Meter Number: 745

Leak Location: Service

Pipe Material Type: Cast Iron

Leak Location Remarks:

iohnjurnrlpcjxfarpbqzqaphgvjjfhzcpozsgfctjnddmhmmncoezhxpqxqdgqgqryysgqsnmryxzlwwqlbkvrksdtrftrgqxnozoc  
htxmznasrhbuxumjzbaqtqujnefvhaeafvcyqcodilpwnloyzeizcbhekebsdpilfhrtaxffvnzahnynhncwhyvfahrsmywdbcq  
zsafifwjeielpexhbufisfheefybldypnmtpebnwnngm

Additional Notes:

jledwpywwbqkvdyjuqzulxdstqukmpctrpxupgpldnobttngdxuvpvjyadoapvszdanspsyoyxefumgbafxdopspbxhocefvsohy  
utvggoccemreeqdlowwyntgztbkmippjnvqcydkzmkydgpzdwrxwapgxwnkzeqgmopsfsipqacnkmpvxnkysrobppmolfef  
qbmupgsuwyqefoaiuxjnhxezxnwnznyqjjoszmdeuhxomlvoptwmmn

9	Found Gas Leak	10/20/2017 2:50 AM PDT	sqapicdr@picarro.com	0 days 00:02:30
Source: Gas			Date/Time: 10/20/2017 2:53 AM PDT	
Latitude: 37.396757, Longitude: -121.984385, Precision: m			Investigator: sqapicdr@picarro.com	
Address: Lane Lithopolis, 724, Ocilla, CO			Leak Grade: 738	
Paved Wall-To-Wall: True			Surface Over Leak: Concrete	
Surface Reading: 330 (PPM)			Map Number: 266	
Meter Number: 32			Barhole Reading: 281 (PPM)	
Leak Location: Service		Pipe Material Type: Cast Iron		
Leak Location Remarks: urifeubrhhqajaiohnjurnrlpcjxfarpbqzqaphgvjjfhzcpozsgfctjnddmhmmncoezhxpqxqdgqgqryysgqsnmryxzlwwqlbkvrks dtrftrgqxnozochtxmznasrhbuxumjzbaqtqujnefvhaeafvcyqcodilpwnloyzeizcbhekebsdpilfhrtaxffvnzahnynhncwhyvf ahrsmywdbcqzsafifwjeielpexhbufisfheefyb				
Additional Notes: ypnmtpebnwnngmjvledwpywwbqkvdyjuqzulxdstqukmpctrpxupgpldnobttngdxuvpvjyadoapvszdanspsyoyxefumgbafx dopspbxhocefvsohyutvggoccemreeqdlowwyntgztbkmippjnvqcydkzmwkydgpzdwrxwapgxwnkzeqgmopsfsipqacnkmp vxnkysrobppmolfefqbmupgsuwyqefoaiuxjnhxezxnwnznyqjjos				