



Copper J Hook - Build Sheet

Visuals

Main Hook Assembly



Copper Part & Bending



Materials & Cuts

- **Hook:** 15" length
- **Carbin:** 5" length
- **Copper:** 12" length
- **Bolts:** 2x (5/16")

Assembly Instructions

- 1 **Bend Copper:** Take the 12" copper piece and bend at the 2 1/2" mark.
- 2 **Weld:** Weld the 5" Carbin piece to the top of the 15" hook piece as shown in the diagram.
- 3 **Attach:** Use the two 5/16" bolts to attach the bent copper part to the main assembly.