

OPEN SOURCE LARGE FORMAT CNC-MACHINE & 3D-PRINTER

David Koch, Sebastian Schütz & Stefan Schütz



2019

Content

1. Introduction.....	2
2. General information	2
3. Design choices	4
3.1 Power.....	4
3.2 Open Build V-wheels	4
3.3 Motors with Trapezoidal Screws	4
3.4 Controller board	5
3.5 Spindle	7
3.6 Motor mounts	8
3.7 Overall design	9
4. Plans	9
4.1 CAD-Design	9
4.2 Wiring Diagram.....	10
4.3 BOM.....	12
4.4 Manual and Instructions (kind of)	13
5. Construction	13
5.1 Modification of the spindle	13
5.2 Machining of the custom parts	13
6. Issues	15
6.1 Z-Axis bending forward	15
6.2 X-Axis not moving.....	15
6.3 Problems during the construction.....	15

1. Introduction

On our school “Birklehof” in Germany, we were offered the possibility to submit a project to the program “Micro-Marco-Mint” of the “Baden-Württemberg-Stiftung” (Baden-Wuerttemberg-Foundation). The “Micro-Macro-Mint”-program supports students interested in mathematics, informatic or engineering with up to 2500€ for their projects. After submitting our application with a first 3D-Model and a Bill of material, we got the funding.

Our goal was to build a large format CNC-machine, with the money available. Due to limited access to a machine shop, we had to rely mostly on screwed connections. This led to the design decision of using aluminium extrusions. The Open Build rails seemed like a perfect fit for our project.

Furthermore we added the option to use the machine as a giant 3D-printer. The wires for the extruder, a stepper motor driver and a sufficient power supply are already installed in the electrical cabinet.

To make this project as open source as possible we used the open builds platform and an Arduino Due with TinyG2 core as controller.

2. General information

The current state of the machine (without the additional Y-axis):




Figure 1: Current state of the machine

The final form:




Figure 2: Final Rendering

The current version isn't behaving according to plan, so we had to do some design tweaks, which should solve these problems. In the section Issues we will talk about those.

The total size of the machine is roughly:

- X: 172 cm
- Y: 172 cm
- Z: 128 cm
- These measurements are measured up to the outer most endpoints. For reference, the MDF-plate on the bottom of the machine measures 150 cm by 125cm. The cable chains are not taken into account

The milling area boils down to:

- X: 116,8 cm
- Y: 112,5cm
- Z: 16,5 cm

While maintaining a weight of ca. 200 kg.

3. Design choices

3.1 Power

A detailed description can be found under Wiring Diagram. First things first. We chose to use three phase power. This is widely available in Germany, so there should be no problems. We did this, because the maximum power output from a normal single phase outlet is about 230V at 16 Amps, which gives you roughly 3680 watts. Considering the four 350 Watt power bricks for the stepper motors and the 1,5 kW spindle, this could get us pretty close to the limit. So we split the main parts over the three phases. One for the spindle, one for the stepper motors and one for the controller and the 3D-printing part. This is also helping to reduce interferences.

3.2 Open Build V-wheels

Our goal was to drive costs down, which was the reason, why we decided to use the V-wheels. Furthermore the lack of a proper machine shop forces us to rely on as many screwed connections as possible, so aluminium extrusions with an integrated linear rail system just came in handy.

The design for the x-axis was borrowed from the linear actuators in the open build store. But the load on the wheels in this design is too high, so they won't turn properly. In the rendering of the final version you can see, that we decided to add an additional Y-axis to spread the load onto more wheels.




Figure 3: <https://openbuildspartstore.com/c-beam-xlarge-linear-actuator-bundle/>

Figure 3: Design template

3.3 Motors with Trapezoidal Screws

The stepper motors are NEMA 34 stepper motors with 12320Z/IN and the 5.6A DM860A drivers. We bought one of these 4 Axis-kits out of china and are quite happy with it. The motors are mounted to our custom motor mounts and are connected to the trapezoidal screws with a normal 12 to 14 mm coupler. The used trapezoidal screws are 12 mm in diameter and have a pitch of 3mm. We decided to use these, because we couldn't get any ball screws in the desired length with this diameter. The main problem was, that all nuts for screws over 12 mm in diameter were too big to be used inside the C-beams.




Figure 4: The holder for the nuts

As you can see in picture four, the space inside the C-beam is filled out by the holder for the nut. The holder was machined on our modified Esel EP 1090 (it now runs on grbl). So 12mm was the maximum we could pack into a c-beam. In hindsight we probably should have used ACME-Screws with the same diameter.

The motor current on the drivers is set to the maximum of 7,8 Amps

1	2	3
OFF	OFF	OFF

and Microstepping is set to 2.

5	6	7	8
ON	ON	ON	ON

3.4 Controller board

The machine is running of TinyG2core version 101. It runs on an Arduino due. All outputs and inputs of the Due are protected via Optocouplers. These furthermore serve as level shifters. The connections are all following the wiring suggested on the official wiki page of tinyG2 and can also be found in the Wiring Diagram. Due to the sad fact, that the Due doesn't have an EEPROM, we have to send all commands on every startup. Here is the list of the current configuration:


```
$ej=0 //Enable text mode
$1mi=2 //Microstepping: 2
$2mi=2
$3mi=2
$1tr=3 //Travel per Revolution: 3mm
$2tr=3
$3tr=3
$lim=1// activate limit switches
```

```
$di1mo=1 // Xmin limit switch activated. Set to active hi (NC)
$di1ac=1 // Stop when hit
$di1fn=1 // Use as limit switch
$di2mo=1 ; Xmax
$di2ac=1
$di2fn=1
```

```
$di3mo=1 ; Ymin
$di3ac=1
$di3fn=1
$di4mo=1 ; Ymax
$di4ac=1
$di4fn=1
```

```
$di5mo=2 ; Zmin - disabled
$di5ac=0
$di5fn=0
$di6mo=1 ; Zmax
$di6ac=1
$di6fn=1
```

```
$xsv=500 // 500mm/min homing speed
$ysv=500
$zsv=500
```

```
$xtm=1168 //Max travel X-axis
$ytm=1125
$ztm=165
```

We are running it with CNCjs and had no problems till now. Every command entered will be validated. We use the left USB-Port on the DUE and it will show up as a Microsoft Serial USB-device.

```
$ej=0  
[ej] enable json mode          0 [0=text,1=JSON,2=auto]  
g2core[mm] ok>
```

Figure 5: Example of a valid command

3.5 Spindle

We use a 1,5 kW china spindle for milling. It is air-cooled and running of a Variable-frequency drive. This allows for a smooth speed control. In comparison to a router (e.g. the typical DeWalt one), it was also easier for us to mount and is pushing more power. The mounts for the spindle had to be bolted to adapter plates we made from 5mm aluminium. There is no plan for these, because it was just some holes. The modification of the plug for the spindle an extra part.




Figure 6: Spindlemount with adapter plates




Figure 7: Spindlemount mounted

3.6 Motor mounts

The motor mounts are custom designed and machined. We made them on our modified ESEL EP 1090 (running of GRBL).




Figure 8: The motor mount without motor

As you can see in the picture they actually serve three purposes:

1. They are connecting elements in the frame
2. The bearings take axial load out from the trapezoidal screw, so that it doesn't destroy the bearings in the motor. In hindsight we learned from a "This Old Tony"-video¹, that there exist tapered roller bearings, which would have been the better choice here.
3. They hold the motors. The motors are mounted with a 5mm threaded rod inside a stainless steel tube.




Figure 9: The motor mounted with the stainless steel tubes

¹ <https://youtu.be/HYOgmhpBUJs?t=277>

This design allowed us to cheat a little bit and saved us the headache of machining a fitting faceplate for the motor. One additional improvement apart from the tapered roller bearings would be to put a screw through the top part of the motor mount. In the picture it seems like the two aluminium plates would be separating, but in reality it is not as bad.

The bearings take the axial load, because we bought nuts for the trapezoidal screw, took one side drilled a small hole and cut a thread for M3 grub screws. The nuts sit one both sides of the bearing and also on the end, where the motor is mounted.




Figure 10: attachment of the TR12-3 screw

3.7 Overall design

We went with a cage like design and till now, it has served as well. We were able to get a surprising amount of precision with the aluminium extrusions. The deviation on the X-Rails is mostly down to measurement errors. The added MDF plates allow for an additional stability, especially the backplate, and serve as a waste board.

4. Plans

4.1 CAD-Design

The design was done in Fusion 360. I exported the model to every format, the export window offered, so that there are no problems with different CAD solutions. Furthermore here is the link, you can use to download the model from Autodesk: <http://a360.co/2y7nwAO> This should give you the most current version.

4.2 Wiring Diagram

The electrical part of the machine is complying with the following regulations:

- 2006-42-EG Maschinenrichtlinie
- BGI5003 Maschinen der Zerspannung
- DIN EN 60204 Elektrische Ausrüstung von Maschinen

Here we got some support from the father of Stefan and Sebastian. The whole construction was done in ePlan P8.

The controls consist of two thermostat controlled ventilated electrical cabinets. One for the Variable-frequency drive of the spindle and one for the actual controls. In the second one are the power supplies, the drivers for the stepper motors, the power supply for the extruder and the Arduino DUE. The USB-port of the DUE is expanded to outside of the cabinet, so that the machine can be run with the cabinets closed.

The extra cabinet for the variable-frequency drive was done due to EMC reasons, so that it wouldn't interfere with the low voltage signals from the Arduino. The parameters for the variable-frequency drive were taken from this very useful site: <http://www.rchobby-net.de/fraese>

The cables and the cable chains were provided by Igus². The used cables are mostly shielded and are designed to be used inside cable chains.

All end positions on the X, Y, and Z-axis are equipped with safety limit switches (Normally closed), which are galvanic isolated through optocouplers, before the signals are interpreted by the Arduino DUE. In order to make the limit switches more resistant to interferences we are using a 12V signal instead of the 3,3V signal which would normally be provided by the Arduino.

² <https://www.igus.de/>




Figure 11: The optocoupler circuit board

The CNC is equipped with two emergency stops, which isolate the machine from main voltage. The Arduino and the optocoupler board are the only ones, which are still provided with their 12V power. There is an additional off-switch, which turns off the machine completely.

The controls for the machine are in the door of the electrical cabinet.

On the larger cabinet are:

- On/Off
- Spindle on/off
- Extruder on/off
- Emergency stop
- Off-Switch

And the smaller on:

- Speed
- Clockwise/0/anti-clockwise rotation



Figure 12: The controls for one/off, ...

The speed control is done with a 10k Ω potentiometer and a 0-10V analog display, where 10V equals 24000 rpm.

After completion the machine was tested according to the regulations by an electrical engineer.

4.3 BOM

The current BOM states 2.308,35 €. In this calculation are not included:

- The wooden plates on the back and the bottom of the machine
- The COMPLETE wiring, because we were sponsored (~1000€. You could cut the price by using cheaper hardware/no-name electronics):
 - o Cable cabinets
 - o Wiring for the cable chains
 - o Cable chains with fitting mounts
 - o Small electric parts (switches, relays, etc. what goes into the electrical cabinet)
- An optional glass bed for using the machine as a 3D-printer

The nuts we used to connect the trapezoidal screw with the C-beam gantry plate also went up significantly in price. We had some with 4 holes in them, but can't find them anymore. The measurements for our nuts are:




Figure 13: The used nuts. [mm]

4.4 Manual and Instructions (kind of)

The document “Aufbauanleitung.pdf” contains pictures from the CAD-Model and some tips, how you could build the CNC. Just to be clear: This isn’t a perfect manual. For example we never added mounts for the cable chains and improvised them. So you should feel comfortable doing such a big project. For reference: The mechanical construction alone took over 100h man-hours. The wiring inside the electrical cabinets plus laying the cables inside the cable chains and hooking them up to their destinations took approximal another 60h. So this is not a weekend project.

5. Construction

5.1 Modification of the spindle

Due to using the inside the maker scene popular china spindle, we realised that the motor is equipped with a CE-certification, but the used 4-pole plug didn’t have a ground wire connected to the metal frame. Furthermore, could be assumed that the used plug only was suitable for low-voltage applications (~60V). To solve these problems, we added a ground connection to the metal frame and changed the plug to a sufficient M17-high power plug rated for 690V at 23A.

The rpm can be controlled between 4000 and 24000 rmp.

5.2 Machining of the custom parts

We had two custom parts. One there the motor mounts and the other was the holder for the nuts. We machined both on our ISEL EP1090 with a 6mm and 3mm bit out of aluminium.




Figure 14: Preparation for machining

We had to machine 16 aluminium plates, but we designed the mounts in a way, so that we only needed 8 files and could use them twice:

- 2x Motormount hinten I (links)
- 2x Motormount hinten II (links)
- 2x Motormount hinten I (rechts)
- 2x Motormount hinten II (rechts)
- 2x Motormount I (Y)
- 2x Motormount II (Y)
- 2x Motormount I (Z)
- 2x Motormount II (Z)

All those files are added. They are 3D-DXFs. If they don't work for you, you can still take the mounts from the 3D model.

Always two plates of the motor mount go together and sandwich on of the bearings in between them.

The holder for the nuts war pretty simple. The hole connecting the holder to the C-beam gantry plate was drilled by hand.

6. Issues

6.1 Z-Axis bending forward




Figure 15: The Z-axis is bending the rods

As someone might be able to see in the picture, the Z-axis is too heavy. It is bending the 5mm rods. That is the reason, why we decided to add the second Y-axis.

6.2 X-Axis not moving

Due to the high load from the Y-axis the wheels running on the X-axis won't turn. We hope to solve this problem by adding the second gantry plate in order to spread out the weight better and minimize the load on each wheel.

6.3 Problems during the construction

- Stainless tubes for the motor mount were too short. You should measure the distance between motor mount and motor with the coupler in-between before cutting of the stainless tubes.
- The screws for the motor mounts are a little bit on the short side, so we had to countersink the holes in the motor mounts