

Shawn's Crazy-Ass EAGLE Hotkeys v1.3

Universal

Commands

ctrl + a	A dd
ctrl + e	Chang E
ctrl + c	C opy
ctrl + x	Cut
ctrl + d	D elete
ctrl + l	Display (L ayers)
ctrl + g	G roup
ctrl + i	I nfo
ctrl + f	Mirror (F lip)
ctrl + m	M ove
ctrl + n	N ame
ctrl + o	O pen
ctrl + v	Paste
ctrl + y	Redo
ctrl + r	R otate
ctrl + h	Smash H
ctrl + b	Split (B end)
ctrl + t	T ext
ctrl + z	Undo
ctrl + u	Val U e
ctrl + s	Write (S ave)

Command Line Tips

Move:	(x y)
Wire:	(x0 y0) (x1 y1) ...

Symbol

Commands

ctrl + p	P in
ctrl + w	W ire

Grids

ctrl + 1	0.1" Lines
----------	------------

Package

Commands

ctrl + p	SMD (P ad)
ctrl + j	Pad (PTH J ump)
ctrl + w	W ire
ctrl + k	Cir K le
ctrl + q	Dimension (Q uantum?)

Grids

ctrl + 1	0.1 mm Dots
ctrl + 2	0.01" Dots

Layers

F1	Top Copper
F2	Bottom Copper
F3	All but tDocu
F4	All but tPlace
F5	All
F6	None

Schematic

Commands

ctrl + q	Label (¿ Q ué?)
ctrl + j	J unction
ctrl + p	Re P lace
ctrl + w	Net (W ire)

Grids

ctrl + 1	0.1" Lines
----------	------------

Board

Commands

ctrl + p	Ratsnest (P our)
ctrl + j	Via (J ump to layer)
ctrl + w	Route (W ire)
ctrl + k	Ripup (K ut!)
ctrl + q	Dimension (Q uantum?)

Grids

Board Outline

ctrl + 1	0.1" Dots
----------	-----------

Part Placement

ctrl + 2	0.05" Dots
----------	------------

Routing

ctrl + 3	0.01" Dots
ctrl + 4	0.001" Dots

Layers

F1	Top Copper
F2	Internal 1 Copper
F3	Internal 2 Copper
F4	Bottom Copper
F5	All
F6	Unrouted Nets
F7	Top Footprints
F8	Bottom Footprints
F9	Top Board
F10	Bottom Board
F11	Whole Board
F12	Toggle Internal Layer