


# PCB Holder connections schematic



The Spindle Probe Cable must be connected to the probe pin on the CNC shield

