



Form Information

Form Name:	Work Order Form
Submitter Name:	Nicolaus Lawson (nicolaus.lawson)
Submission Date:	Feb 15, 2017 5:30:02 PM COT
Server Receive Date:	Feb 15, 2017 5:30:09 PM COT
Reference Number:	20170215-1855376318
Location:	Leinster Rd, Kingston, Jamaica Feb 15, 2017 5:30:00 PM COT [View Map]

Work Order

Date	Feb 15, 2017
Supervisor	Franklyn Saunders
Crew	VA2 (Valve team #2)
Zone office	Rock Point
Road	Leinster Rd, Kingston, Jamaica Feb 15, 2017 5:02:38 PM COT [View Map]
Leak status	Leak found
Excavation required?	No

Before Repair

Is the leak visible?	Yes
Observation	Pedestrian area Service connection
Origin of the leak	Valve

Leak Survey (Valve)

Type of valve	Butterfly valve
Location of leak (valve)	Stem
Cause of leak (valve)	Normal wear Corrosion Poor installation
Pipe size (inch/mm)	226
Pipe material	CI
Pipe circumference (mm)	335
OD (mm)	106.63
OD (inch)	4.20

Saddle

Saddle	4x3/4
Description:	4"x3/4" BSPT Brass w/SS Single Strp Sadle 3846BSPT C900 4.80
Quantity	1


Ball Valve

Quantity	0
<hr/> Elbow 90°	
Quantity	0
<hr/> ISIFLO Coupling Straight	
Quantity	0
<hr/> ISIFLO Coupling Elbow 90°	
Quantity	0
<hr/> Insert for PEX	
Quantity	0
<hr/> PEX Pipe	
Length (cm)	0
<hr/> Meter Valve	
Quantity	0
<hr/> Manifold	
Quantity	0
<hr/> Cap for Manifold	
Quantity	0
<hr/> Clamp	
Quantity	0
<hr/> Flex Adaptor	
Quantity	0
<hr/> Detection Tape	
Detection tape	67T06W-Detecto Tape
Description:	Detecto Tape Water
Length (cm)	15
<hr/> Reinstatement	
Bedding	Yes
Back filling	Yes
Compaction	No
Outstanding ground works	
Asphalt works	Yes
Concrete works	Yes
Sidewalk works	Yes
Sidewalk curb works	Yes


Job Closed

I verify that the above information is complete and accurate.

Site supervisor signature (Miya)

A handwritten signature consisting of a series of loops and a final horizontal stroke.

Team leader signature (NWC)

A handwritten signature consisting of several overlapping, curved strokes.

Date/Time

Feb 15, 2017 5:29:55 PM COT