

## Form Information

Form Name:	<b>Work Order Form</b>
Submitter Name:	Nicolaus Lawson (nicolaus.lawson)
Submission Date:	Feb 15, 2017 4:52:06 PM COT
Server Receive Date:	Feb 15, 2017 4:52:16 PM COT
Reference Number:	20170215-1855374075
Location:	Leinster Rd, Kingston, Jamaica Feb 15, 2017 4:51:59 PM COT [ <a href="#">View Map</a> ]

## Work Order


Date	Feb 15, 2017
Supervisor	Franklyn Saunders
Crew	MO2 (Mona team #2)
Zone office	Mona
Road	Leinster Rd, Kingston, Jamaica Feb 15, 2017 4:50:01 PM COT [ <a href="#">View Map</a> ]
Property #	34 elm
Meter #	1232
Leak status	Leak found
Excavation required?	Yes

## Before Excavation


Is the leak visible?	Yes
Observation	Street

## After Excavation

Origin of the leak	Main
Pre-repair photos	



Pre-repair sketch photos



### Leak Survey (Main)

Failure type (pipe)	Pin hole
Failure type (fittings)	Elbow
Cause of leak	Corrosion Poor instalation Soil settlement Tree roots
Pipe material	DI
Pipe size (inch/mm)	26
Pipe circumference (mm)	355
OD (mm)	113.00
OD (inch)	4.45

### Saddle

Saddle	4x1-1/2
Description:	4"x1-1/2" BSPT Brass Single Strap Saddle 3846BSPT C900 4.80
Quantity	4

### Ball Valve

Ball valve (at saddle)	Ball Valve DZR. 1"F X 1"M
Description:	Ball Valve DZR. 1"F X 1"M
Quantity	2

### Elbow 90°

Elbow 90° (at saddle)	Elbow 90 DZR. Male x Female 1"X1"
Description:	Elbow 90 DZR. Male x Female 1"X1"
Quantity	3

### ISIFLO Coupling Straight


Quantity	0
----------	---

### ISIFLO Coupling Elbow 90°

Quantity	0
----------	---

### Insert for PEX

Quantity	0
<hr/>	
PEX Pipe	
Length (cm)	0
<hr/>	
Meter Valve	
Quantity	0
<hr/>	
Manifold	
Quantity	0
<hr/>	
Cap for Manifold	
Quantity	0
<hr/>	
Clamp	
Quantity	0
<hr/>	
Flex Adaptor	
Quantity	0
<hr/>	
Detection Tape	
Detection tape	67T06W-Detecto Tape
Description:	Detecto Tape Water
Length (cm)	33
<hr/>	
Reinstatement	
Bedding	Yes
Back filling	Yes
Compaction	No
Outstanding ground works	
Asphalt works	Yes
Concrete works	Yes
Sidewalk works	Yes
Sidewalk curb works	Yes
<hr/>	
After Repair Photos/Remarks	
<hr/>	
Post Repair Photos	



Remarks

thanks

Job Closed

---

I verify that the above information is complete and accurate.

Site supervisor signature (Miya)

Team leader signature (NWC)

Date/Time

Feb 15, 2017 4:51:55 PM COT

Remarks

worlcome