




























ASSEMBLY INSTRUCTIONS




Part List

				
① x2Pcs	② x2Pcs	③ x1Pc	④ x1Pc	⑤ x1Pc
				
⑥ x2Pcs	⑦ x1Pc	⑧ x1Pc	⑨ x1Pc	⑩ x1Pc
				
⑪ x4Pcs	⑫ x1Pc	⑬ x1Pc	⑭ x1Pc	

Hardware List

					
M6x30	M6x60	M6x12		M6x28	
Ax36Pcs	Bx6Pcs	Cx2Pcs	Dx10Pcs	Ex6Pcs	Fx2Pcs
					
Gx1Pc	Hx1Pc	M6x60 Ix1Pc	M4x10 Jx2Pcs	Kx1Pcs	




PLEASE BE CAREFUL. DO NOT DAMAGE THE HOLE POSITION WHEN YOU USE POWER TOOLS !

Step 1




M6



Ex6Pcs



Step 2



↓ or ↑



Hx1Pc



M6x30


Ax12Pcs



M6x60

Ix1Pc

Step 3



Gx1Pc



Hx1Pc




Dx4Pcs




M6x30


Ax4Pcs






↓ or ↑




Step 4




	
Hx1Pc	M6x30 Ax12Pcs



↓ or ↑



Step 5




Hx1Pc




M6x30

Ax2Pcs



Step 6




Hx1Pc



M6x30

Ax4Pcs



Step 7




Hx1Pc










M6x30

Ax2Pcs






Step 8

				
Gx1Pc	Hx1Pc	Dx6Pcs	M6x12 Cx2Pcs	M6x60 Bx6Pcs
				
				Fx2Pcs



Step 9

		
Hx1Pc	Jx2Pcs	Kx1Pcs

