




**This document is our property and shall not be altered, copied, used for manufacturing or communicated to any other person or company without our permission**



NOTES:



TUTTI I BORDI DEVONO ESSERE ESENTI DA BAVE  
ALL THE EDGES MUST BE BURR FREE

SUPERFICI ESENTI DA AMMACCATURE, OLIO, COLLA, GRAFFI E ALTRI DIFETTI  
SURFACES MUST BE FREE FROM DENTS, OIL, GLUE, STICKER AND OTHER DEFECTS

I LEMBI DEVONO ESSERE ACCOSTATI PER EVITARE FESSURE E SALDATI  
THE EDGES MUST BE PULLED TOGETHER TO AVOID CHINK AND WELDED

*E' AMMESSA L'ESECUZIONE DI SCANTONATURE/DENTI/SPINE DI RIFERIMENTO PER FACILITARE IL POSIZIONAMENTO E IL PROCESSO DI SALDATURA  
REFERENCE CARVES/TEETH OR PINS ARE ALLOWED IN ORDER TO GUARANTEE THE RIGHT POSITIONING AND PROPER WELDING PROCESS*

**Additional Notes:** PSD6104B.01 con trattamento diverso

[illegible]