



Material Safety Data Sheet

FIR No.: 169305
Version Number: US-US-2

Level: 1
Release Date: 2009-07-29

Storage: Technical Measures:

Guard against dust accumulation of this material. Shipping and storage may result in accumulation of dust in shipping containers. If this occurs, dispose of the container in an airtight polyethylene bag of remove dust by vacuuming or wet mopping. Vacuums used for this purpose should be equipped with HEPA filters. Do not use compressed air to blow dust from storage containers.

Storage Conditions:

Store in a ventilated, dry storage area away from corrosive materials (acids and bases) or oxidizers.

8. Exposure Controls/Personal Protection

Engineering Measures:

Use adequate ventilation to control airborne concentrations below the exposure limits/guidelines. If user operations generate a vapor, dust, and/or mist, use process enclosure, local exhaust ventilation, or other engineering controls to control airborne levels below the recommended exposure limits/guidelines. Eyewash and emergency showers are recommended.

Exposure Limits:

Chemical Name	TWA	STEL/C	References	Notes
MAGNESIUM OXIDE	10(mg/m3)		ACGIH	
ZINC OXIDE		15(ppm)	OSHA ACGIH	
	Note		OSHA	Total dust 15 mg/m3; Respirable fraction 5 mg/m3

Personal Protective Equipment:

Respiratory Protection:

Use a HEPA dust particulate filter respirator for concentrations exceeding the Occupational Exposure Limit.

Hand Protection:

Use appropriate hand protection.

Eye Protection:

Wear safety glasses.

Skin and Body Protection:

Light protective clothing is recommended.

Hygiene Measures:

Wash thoroughly after handling.