



Inspection Report

Order No: #8168127

Date: 23-05-2023

Customer Deatils

Buyer Details

Buyer Name : Mahindra Singh

Buyer Number: 9562341753

Location: Thane


Seller Details

Seller Name : Madhvi Bhide

Seller Number: 9563241563















Location: Kalyan West

Car Body Evaluation









Inspection Report

 Headlight	 Turn Signal
 Handle	 Wheel
 Fuel Cap	 Rear Bumper
 Bonnet	 Roof
 Wind Shield	 Dicky
 Quarter Panel	 Bonnet, Back Door
 Front Door	 Front Bumper

RC and Insurance Details

RC	RC Type
 <p>Original</p>	 <p>Private</p>
Insurance Type	Expiry Date
 <p>Zero Dep Insurance</p>	 <p>2023-06-18</p>

Chassis Details

Chassis No	Engine No
MA3ETDE1S00522954	K10BN2143497
	



Inspection Report

Vehicle Details

Vehicle State	MH
Vehicle Number	MH05DS2670
Vehicle Make	Maruti suzuki
Vehicle Model	Celerio
Variant	VXI
MFG Year	2018-05-01
REG Year	2018-06-27
Tax Validity	2033-06-26
Colour	Gray
Engine Cubic Capacity	998
Fuel type	Petrol
Owner Serial No	01
Odometer Reading	35382
Accidental Summary	No
Flooded Condition	No
Special Comments	MH05, Actual Colour is Glistening Grey

Uploaded Photos

Front View



Front Glass



Engine Compartment



Roof



Front RHS side Triangle View



Front RHS Tyre



Inspection Report

RHS side View



RHS side Interior View




Rear RHS tyre



Back side View



Dicky Door Open View



Dicky Floor View



Inspection Report

Rear Glass



Spare Wheel tyre



Rear LHS side Triangle View




Rear LHS Tyre






LHS side View







Rear interior View











Front LHS tyre	Dashboard View
	
Odometer View	
	





Exterior Front Side


Front Bumper	Bonnet
 <p>Original, Minor Scratches</p>	 <p>Original, Minor Scratches, Minor Dent</p>
Front Glass	Roof
 <p>Original</p>	 <p>Original, Minor Scratches, Minor Dent</p>

Exterior RHS Side





RHS side Apron	Front RHS Tyre percentage
 <p>Original</p>	 <p>50%</p>
RHS Fender	A Pillar
 <p>Original, Minor Scratches, Major Dent</p>	 <p>Original</p>

B Pillar	Front RHS Window
 <p>Original</p>	 <p>Original, working</p>
Front RHS Door	Rear RHS Door
 <p>Original, Minor Scratches</p>	 <p>Original, Minor Scratches</p>

Rear RHS Window	RHS Running board
 <p>Original, working</p>	 <p>Original, Minor Scratches, Major Dent</p>
C Pillar	Rear RHS Tyre percentage
 <p>Original</p>	 <p>70%</p>

RHS Quater panel	
 <p>Original, Minor Scratches, Rusted</p>	

Exterior Back Side





Dicky Door	Rear Glass
 <p>Original, Major Scratches, Minor Dent</p>	 <p>Original</p>
Dicky Floor Condition	Spare Wheel Tyre percentage
 <p>Original</p>	 <p>50%</p>





Rear Bumper







Original, Minor Dent, Major Scratches

Exterior Lhs side

Lhs side Apron	Front Lhs Tyre percentage
 <p>Original</p>	 <p>50%</p>
Lhs Fender	A Pillar
 <p>Original, Minor Scratches, Major Dent</p>	 <p>Original</p>

B Pillar	Front LHS Window
 <p data-bbox="395 920 496 954">Original</p>	 <p data-bbox="1042 936 1257 969">Original, working</p>
Front LHS Door	Rear LHS Door
 <p data-bbox="164 1612 727 1646">Original, Minor Scratches, Repainted, Rusted</p>	 <p data-bbox="914 1628 1382 1662">Original, Minor Scratches, Major Dent</p>

Rear LHS Window	LHS Running board
 <p>Original, working</p>	 <p>Original, Minor Dent, Major Scratches</p>
C Pillar	Rear LHS Tyre percentage
 <p>Original</p>	 <p>50%</p>

LHS Quater panel



Original, Major Scratches, Major Dent



Inspection Report

Interior

Airbag	Yes
ABS	Yes
Music System	Yes
Speaker	Working
Steering Wheel condition	Good
Steering Wheel Audio Control buttons	Working
Auto AC Condition	NA
Ac Flow	Working
Ac Blower motor condition	Working
Ac Direction Mode	Working
Ac Heater	Working
Glow Box	Working
Gear Lever Knob	Good
Power Window	Yes
RHS side Seat	Good
LHS side Seat Condition	Good
Rear seat Condition	Good
All seat cover Available	Yes
All Mats Available	Yes



Inspection Report

Test Drive

Front Suspension	No
Axle Noise	No
Rear suspension Noise	No
Clutch Condition	Ok
Automatic Gear Box	Not Available
Gear Box	Manual
Gear Box Noise	Yes
Gear Shifting	Ok
Wheel Alignment	Ok
Steering Noise	Yes
Steering Column noise	Yes
Speedometer Knob	Working
Odometer Reading	Working








Inspection Report

Engine Compartment

Tappet Noise	No
Engine overheating	No
Engine oil Sludge	No
Engine oil Condition	Good
Coolent	Good
Timeing Side Noise	No
Alternater Noise	Ok
Battery condition	Good
Ac compressor	Ok
Starter motor Noise	No
Air Filter Assy	Ok
Video	Video Link

Special Feature

Comment 1	Photo
Display Touch screen Music system	
Comment 2	Photo
Rear view Camera	
Comment 3	Photo
One Key	

Comment 4	Photo
<p>Driver side Airbag</p>	
Comment 5	Photo
<p>Power windows</p>	



Inspection Report

Extra Damage

Comment 1	Photo
Cowl panel Grill broken	
Comment	
Brake condition - Ok , Smoke Condition - Ok , Back compression - Ok	

Disclaimer

- 1) All information in the report are depends on the facts at the time of inspection & Autoscal cannot be held responsible for any discrepancy in the mentioned facts. Autoscal has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.
- 2) Ownership documents of the vehicle were verified by the Inspection engineer, Autoscal is not responsible for validating the authenticity of the document.
- 3) This inspection report was generated by Autoscal based on the request raised by the party, whom the report is addressed to, for the stated purpose only. The above inspection is valid for 24hrs.