
















**Order No:** #63147





**Date:** 30-05-2023

## Car Body Evaluation





 Headlight	 Turn Signal
 Handle	 Wheel
 Fuel Cap	 Rear Bumper
 Bonnet	 Roof
 Wind Shield	 Dicky
 Quarter Panel	 Bonnet, Back Door
 Front Door	 Front Bumper

## RC and Insurance Dsetails

RC	RC Type
<p data-bbox="193 501 507 524">Image not found or type unknown</p>  <p data-bbox="397 1032 491 1061">Original</p>	<p data-bbox="898 501 1212 524">Image not found or type unknown</p>  <p data-bbox="1104 1032 1193 1061">Private</p>
Insurance Type	Expiry Date
<p data-bbox="193 1189 507 1211">Image not found or type unknown</p>  <p data-bbox="320 1720 568 1749">Zero Dep Insurance</p>	<p data-bbox="898 1189 1212 1211">Image not found or type unknown</p>  <p data-bbox="1082 1720 1217 1749">2030-08-25</p>



Chassis Details

Chassis No	Engine No
jxjxjkx	jfjfj
<div>Image not found or type unknown</div> 	<div>Image not found or type unknown</div> 









# Inspection Report

## Vehicle Details


Vehicle State	AP
Vehicle Number	jcjj
Vehicle Make	MG
Vehicle Model	Hector
Variant	ncnc
MFG Year	2023-06-23
REG Year	2023-06-28
Tax Validity	2023-06-23
Colour	Gray
Engine Cubic Capacity	7178
Fuel type	Petrol
Owner Serial No	67
Odometer Reading	3637
Accidental Summary	Yes
Flooded Condition	Yes
Special Comments	hxhxj
Hypothecation	Yes
Bank Name	idbi

## Uploaded Photos

<p><b>Front View</b></p>	<p><b>Front Glass</b></p>
<p>Image not found or type unknown</p> 	<p>Image not found or type unknown</p> 
<p><b>Engine Compartment</b></p>	<p><b>Roof</b></p>
<p>Image not found or type unknown</p> 	<p>Image not found or type unknown</p> 
<p><b>Front RHS side Triangle View</b></p>	<p><b>Front RHS Tyre</b></p>
<p>Image not found or type unknown</p> 	<p>Image not found or type unknown</p> 


**RHS side View**

Image not found or type unknown




**RHS side Interior View**

Image not found or type unknown




**Rear RHS tyre**

Image not found or type unknown




**Back side View**

Image not found or type unknown




**Dicky Door Open View**







Image not found or type unknown



**Dicky Floor View**




Image not found or type unknown



<p><b>Rear Glass</b></p>	<p><b>Spare Wheel tyre</b></p>
<p>Image not found or type unknown</p> 	<p>Image not found or type unknown</p> 
<p><b>Rear LHS side Triangle View</b></p>	<p><b>Rear LHS Tyre</b></p>
<p>Image not found or type unknown</p> 	<p>Image not found or type unknown</p> 
<p><b>LHS side View</b></p>	<p><b>Rear interior View</b></p>
<p>Image not found or type unknown</p> 	<p>Image not found or type unknown</p> 







# Inspection Report





Front LHS tyre	Dashboard View
<div>Image not found or type unknown</div> 	<div>Image not found or type unknown</div> 
Odometer View	
<div>Image not found or type unknown</div> 	











## Exterior Front Side


Front Bumper	Bonnet
<p data-bbox="193 501 507 524">Image not found or type unknown</p>  <p data-bbox="284 1028 604 1061">Original, Minor Scratches</p>	<p data-bbox="898 501 1212 524">Image not found or type unknown</p>  <p data-bbox="1010 1028 1291 1061">Repainted, Major Dent</p>
Front Glass	Roof
<p data-bbox="193 1189 507 1211">Image not found or type unknown</p>  <p data-bbox="323 1718 564 1751">Replace, Scratches</p>	<p data-bbox="898 1189 1212 1211">Image not found or type unknown</p>  <p data-bbox="1010 1718 1291 1751">Minor Dent, Repainted</p>

## Exterior RHS Side





RHS side Apron	Front RHS Tyre percentage
<p data-bbox="193 501 507 524">Image not found or type unknown</p>  <p data-bbox="347 1028 544 1061">Original, Repair</p>	 <p data-bbox="1123 1046 1177 1079">10%</p>
RHS Fender	A Pillar
<p data-bbox="193 1191 507 1214">Image not found or type unknown</p>  <p data-bbox="306 1718 584 1751">Major Dent, Repainted</p>	<p data-bbox="898 1191 1212 1214">Image not found or type unknown</p>  <p data-bbox="1072 1718 1225 1751">dent, Repair</p>


B Pillar	Front RHS Window
<p data-bbox="193 398 512 421">Image not found or type unknown</p>  <p data-bbox="368 925 520 954">dent, Repair</p>	 <p data-bbox="1015 943 1278 972">not working, Replace</p>
Front RHS Door	Rear RHS Door
<p data-bbox="193 1086 512 1108">Image not found or type unknown</p>  <p data-bbox="304 1615 584 1644">Minor Dent, Repainted</p>	<p data-bbox="898 1104 1217 1126">Image not found or type unknown</p>  <p data-bbox="1007 1630 1286 1659">Minor Dent, Repainted</p>

Rear RHS Window	RHS Running board
 <p>Replace, working</p>	<p>Image not found or type unknown</p>  <p>Major Scratches, Repainted</p>
C Pillar	Rear RHS Tyre percentage
<p>Image not found or type unknown</p>  <p>Repair, Original</p>	 <p>10%</p>





RHS Quater panel	
<p data-bbox="193 398 512 421">Image not found or type unknown</p>  <p data-bbox="300 925 592 958"><b>Major Dent, Minor Dent</b></p>	

## Exterior Back Side





Dicky Door	Rear Glass
 <p>Original, Minor Scratches</p>	 <p>Cracked, Scratches</p>
Dicky Floor Condition	Spare Wheel Tyre percentage
 <p>Major Dent, Damage</p>	 <p>10%</p>





Rear Bumper	
<p data-bbox="193 398 512 421">Image not found or type unknown</p>  <p data-bbox="263 925 622 954"><b>Major Scratches, Minor Dent</b></p>	


## Exterior Lhs side

Lhs side Apron	Front Lhs Tyre percentage
<p>Image not found or type unknown</p>  <p>Original, Repair</p>	 <p>30%</p>
Lhs Fender	A Pillar
<p>Image not found or type unknown</p>  <p>Repainted, Minor Scratches</p>	<p>Image not found or type unknown</p>  <p>dent, Rusted</p>



B Pillar	Front LHS Window
<p data-bbox="193 398 512 421">Image not found or type unknown</p>  <p data-bbox="368 925 520 958">dent, Repair</p>	 <p data-bbox="1042 940 1257 974">Original, Replace</p>
Front LHS Door	Rear LHS Door
<p data-bbox="193 1088 512 1111">Image not found or type unknown</p>  <p data-bbox="212 1615 683 1648">Original, Minor Scratches, Minor Dent</p>	<p data-bbox="898 1104 1217 1126">Image not found or type unknown</p>  <p data-bbox="987 1630 1307 1664">Original, Minor Scratches</p>

Rear LHS Window	LHS Running board
 <p>not working, working</p>	<p>Image not found or type unknown</p>  <p>Minor Dent, Repainted</p>
C Pillar	Rear LHS Tyre percentage
<p>Image not found or type unknown</p>  <p>dent, Repair</p>	 <p>10%</p>

LHS Quater panel	
<p data-bbox="193 398 512 421">Image not found or type unknown</p>  <p data-bbox="304 925 584 958"><b>Major Dent, Repainted</b></p>	



## Interior

Airbag	Yes
ABS	Yes
Music System	No, Yes
Speaker	Working
Steering Wheel condition	Good
Steering Wheel Audio Control buttons	Working
Auto AC Condition	NA, No
Ac Flow	Working
Ac Blower motor condition	Not Working
Ac Direction Mode	Working
Ac Heater	Working
Glow Box	Working
Gear Lever Knob	Good
Power Window	Yes
RHS side Seat	Good
LHS side Seat Condition	Bad
Rear seat Condition	Good
All seat cover Available	Yes
All Mats Available	Yes



# Inspection Report

## Test Drive

Front Suspension	No
Axle Noise	Yes
Rear suspension Noise	Yes
Clutch Condition	Jaddring, Sepage
Automatic Gear Box	Not Available, Jerking
Gear Box	Manual
Gear Box Nosie	Yes
Gear Shifting	Ok
Wheel Alignment	Ok
Steering Noise	Yes
Steering Colum noise	Yes
Speedometer Knob	Working
Odometer Reading	Working



# Inspection Report


## Engine Compartment

Tappet Noise	Yes
Engine overheating	Yes
Engine oil Sludge	Yes
Engine oil Condition	Good, Bad
Coolent	Leakage, Bad
Timeing Side Noise	Yes
Alternater Noise	Ok
Battery condition	Good
Ac compressor	Not Working, Noise
Starter motor Noise	Yes
Air Filter Assy	Ok
Video	<a href="#">Video Link</a>



# Inspection Report

## Special Feature

Comment 1	Photo
jdjdj	



# Inspection Report

## Extra Damage

## Disclaimer

- 1) All information in the report are depends on the facts at the time of inspection & TCD cannot be held responsible for any discrepancy in the mentioned facts. TCD has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.
- 2) Ownership documents of the vehicle were verified by the Inspection engineer, TCD is not responsible for validating the authenticity of the document.
- 3) This inspection report was generated by TCD based on the request raised by the party, whom the report is addressed to, for the stated purpose only. The above inspection is valid for 24hrs.