



Fatigue

Samudra Dasgupta

Senior Lecturer in Aerospace Engineering
University of Bristol

bristol.ac.uk



Fatigue

Part-3: Fatigue prevention

bristol.ac.uk



Fatigue life

$$N = N_{\text{stage-1}} + N_{\text{stage-2}} + N_{\text{stage-3}}$$

$$N = N_{\text{initiation}} + N_{\text{slow propagation}} + N_{\text{fast propagation}}$$

$$N = N_i + N_{SP}$$

(since fast propagation time is negligible)








Prevent crack initiation / increase Ni

- Crack initiates when $S_{\text{local}} > YS$
- To reduce chance of crack initiation
 - Use material with higher YS
 - Stronger materials
 - Strengthening mechanisms
 - Lower S_{local} by reducing stress concentrations
 - Good surface finish
 - Proper component design (no abrupt changes in cross section, no sharp corners or edges etc.
 - No microscopic defects like porosity, cavity, non-metallic inclusions (use advanced manufacturing like vacuum melting, ESR, prepregs etc.)

Fatigue notch sensitivity


- Notch fatigue strength reduction factor (K_f) = fatigue strength without notch / fatigue strength with notch
 - \neq Material property (depends on size, shape, stress etc.)
- Fatigue notch sensitivity parameter (q) = $(K_f - 1) / (K_t - 1)$
 - K_t = Monotonic notch concentration factor
 - Highest notch sensitivity ($q = 1$) when $K_f = K_t$
 - Least notch sensitivity ($q = 0$) when $K_f = 1$
 - Only indicative

Few unique stress raisers in composites



Delay slow propagation of crack / increase N_{SP}


- da/dN = (crack advancement – crack closure)
 - To reduce crack advancement: Higher YS (lower plastic deformation)
 - To increase crack closure: Higher plastic deformation (lower YS)
 - Contradictory requirement needing optimization
 - Surface / case hardening
 - Residual compressive stresses



Residual compressive stresses

- Recall: Compressive mean stress improves fatigue life

- Tension: opens up crack
- Compression: Closes crack







- Residual stress

- Shot peening / sand blasting (10x fatigue life for mild steel)
- Cold worked holes (with oversized mandrel pull through)
- Overloads (tensile overload leaves compressive residues): e.g. freak gust, emergency maneuvers, heavy landings etc.

- Need to be careful about relaxation effects with cyclic loading / heating

bristol.ac.uk



End of Part-3

Fatigue

bristol.ac.uk



Thank you

samudra.dasgupta@bristol.ac.uk

<https://in.linkedin.com/in/samudradg>

bristol.ac.uk

