



Title: Fixing the roof

Date: 2023-04-

Accuracy:

ELECTRO VOLT
SUSTAINABLE ENERGY



Electro Volt Technician: Bob Baumeister

Functional Location: Garching

Description: Splicer Repairs 4058216

Code Word Equipment:

Description Equipment:
Number:

Subject Service:
Order Customer: 2410011
No. Operation: 0020
No. Notification: 000300113570
No. Type: Field Service
Period: 25.02.2023 - 01.03.2023

Date: 2023-04-3

Description of the problem / maintenance / inspection

Roof had a leak and was dripping

Reason and solution of the problem / accomplished work

- noticed several problems with the roof, including missing shingles, cracked shingles, and loose flashing around the chimney.
- removed the damaged shingles and replaced them with new ones, using roofing cement to secure them in place.
- repaired the cracked shingles by carefully applying roofing sealant to each crack to prevent water from penetrating the roof.
- replaced the old, damaged flashing around the chimney with new flashing and used roofing sealant to secure it in place.