



Title: Fixing the roof

Date: 2023-04-

Accuracy:

**ELECTRO VOLT**  
SUSTAINABLE ENERGY



Electro Volt Technician: Bob Baumeister

Functional Location: Garching  
Description: Splicer Repairs 4058216

Code Word Equipment:

Description Equipment:  
Number:

Subject Service:  
Order Customer: 2410011  
No. Operation: 0020  
No. Notification: 000300113570  
No. Type: Field Service  
Period: 25.02.2023 - 01.03.2023

Date: 2023-04-3

Description of the problem / maintenance / inspection

Roof had a leak and was dripping

Reason and solution of the problem / accomplished work

arrived at 8:30 noticed several problems with the roof missing and cracked shingles, and loose flashing around the chimney. removed the damaged shingles and replaced them with new ones, using roofing cement to secure them in place.