


Lab: Motor Driver Board Population


Objective

- Solder and insert all components to motor driver, in the correct order

DriveBot Overview



Motor Driver Close-Ups



Components

Solder all like components in the order indicated in the following diagram (numbers 1, 2, 3, and 4). Take note that the op-amps (#5) will not be soldered; rather, you will insert one into each IC socket once you complete the soldering.

