

IMPORTANT: FROM NOW ON, DO NOT FLIP THE RUN SWITCH DOWN UNTIL YOU ARE TOLD TO DO SO. TAPE I/O IS AUTOMATIC AND THE COMPUTER MUST NOT BE RESET DURING ANY PART OF THE ASSEMBLY PROCEDURE TO FOLLOW.

Whenever you hear the quick series of beeps during the first pass of assembly, you have two choices:

- 1) Key 1 -- continue (or start) first pass
- 2) Key 2 -- begin second pass

You are now ready to read in the first of the two sections of the source listing from tape. Press Key 1. The screen will go blank indicating the computer has entered the tape read mode. Start the tape. After the first section has been entered and processed, the display will come back on, and the quick series of beeps will again be heard. Stop the tape before the next section begins to play. (Use "pause" if you have it.)

Once again, press Key 1 and restart the tape, playing in the second section of the source listing which you have recorded. This completes the first pass. DO NOT TOUCH THE RUN SWITCH!

After you become familiar with its operation, you won't have to stop the tape in between sections as long