



-3/8-16 UNC - 2B TAP THRU
5/16 DRILL (0.313) THRU

TOLERANCES DECIMALS ANGLES XX = ±0.01 X = ±5 XXX = ±0.001 XX = ±0.5 XXXX = ±0.0001 XXX = ±0.50 XXXXXX = ±0.00001		COLLEGE OF ENGINEERING UNIVERSITY OF NORTH DAKOTA		
DATE ISSUED: Jan-08-23		COLLECTOR_HINGE2CHASSIS_GJS		
DRAWN BY: Gabriel Schettler		SIZE C	COURSE : SECTION :	DWG NO COLLECTOR_HINGE2CHASSIS
CHECKED BY:		SCALE 1.000	MATERIAL AL6061	SHEET 1 OF 1

