


Bug: not all pins
are 1/0 !!

Eco: 4 cuts
4 wires



TODO:
pin connections for PIO have changed
relative to my existing .ino and hw.
Serial connections are OK
Future revision: add a GND lug for 'scope



SD-card Adaptor for connection to NASCOM1 or NASCOM2 PIO or serial interface.

foofobedoo@gmail.com

Sheet: /
File: nascom_sd.sch

Title:

Size: A4	Date: 18-Aug-2019
----------	-------------------

Rev: 1/1